



Engineering - Landscape Architecture - Surveying

7 Waldo Street, St. Augustine, FL 32084 | 904.826.1334 | www.matthews.dccm.com

mdg.cei@dccm.com

LICENSE #26535, LB8590, LA6666877

General Information

Project Name	24015 Double Branch CDD		
Prepared By	Mike Silverstein		
Date Of Visit	12/02/2024 2:03 PM EST		
Date Prepared	12/02/2024 EST		
Weather	Clear	Temp	61
Site Conditions		Date of Last Report	N/A
Present at Site			

Site Notes

Mike Silverstein December 2, 2024 2:20 PM EST
Report revised per CDD boundary.

Corrected since last report

N/A

Observations

Drainage

1 Structure functioning as designed.

2 Structure operating as designed.

3 Structure operating as designed.

4 Structure operating as designed.

6 Structure operating as designed.

Observations

9 20 Structure is functioning as designed.

Storm

9 20 Structure is functioning as designed.

Needs Action

Drainage

7 11 Possible clog at both curb inlets, storm water staging up into gutter and roadway.

Landscape

5 7 Animal burrow found on pond bank - Consult with environmental on animal species (possible gopher tortoise) or if active.

8 13 Animal burrow - Consult with environmental on animal species (possible gopher tortoise) - Mentioned in Item #7.

Misc


5 7 Animal burrow found on pond bank - Consult with environmental on animal species (possible gopher tortoise) or if active.

8 13 Animal burrow - Consult with environmental on animal species (possible gopher tortoise) - Mentioned in Item #7.

Storm

7 11 Possible clog at both curb inlets, storm water staging up into gutter and roadway.

Map Overview



Action Items



1

Observation

Pin Type: General

Categories:

Drainage


Location:

Created by:



Mike Silverstein
Senior Construction Inspector

Sep 13, 2024 at 8:37 am EST



Notes:

Mike Silverstein September 13, 2024 8:37 AM EST

Structure functioning as designed.

Photos:



Sep 12, 2024 at 3:40 pm EST



Sep 12, 2024 at 3:40 pm EST



Sep 12, 2024 at 3:40 pm EST



4

Observation

Pin Type: General

Categories:

Drainage


Location:

Created by:



Mike Silverstein
Senior Construction Inspector

Sep 13, 2024 at 8:43 am EST



Notes:

Mike Silverstein September 13, 2024 8:43 AM EST

Structure operating as designed.

Photos:



Sep 12, 2024 at 3:51 pm EST



Sep 12, 2024 at 3:51 pm EST



Sep 12, 2024 at 3:51 pm EST



5

Observation

Pin Type: General

Categories:

Drainage


Location:

Created by:



Mike Silverstein
Senior Construction Inspector

Sep 13, 2024 at 8:56 am EST




Notes:

Mike Silverstein September 13, 2024 8:56 AM EST

Structure operating as designed.

Photos:



Sep 12, 2024 at 3:52 pm EST



Sep 12, 2024 at 3:52 pm EST



Sep 12, 2024 at 3:52 pm EST

3

5

Observation *(continued)*

Pin Type: General


Created by:



Mike Silverstein
Senior Construction Inspector

Sep 13, 2024 at 8:56 am EST

Photos:





6

Observation

Pin Type: General

Categories:

Drainage


Location:

Created by:



Mike Silverstein
Senior Construction Inspector

Sep 13, 2024 at 8:57 am EST



Notes:

Mike Silverstein September 13, 2024 8:57 AM EST

Structure operating as designed.

Photos:



Sep 12, 2024 at 3:55 pm EST



Sep 12, 2024 at 3:55 pm EST



Sep 12, 2024 at 3:55 pm EST

4

6

Observation *(continued)*

Created by:




Mike Silverstein
Senior Construction Inspector

Pin Type: General

Sep 13, 2024 at 8:57 am EST

Photos:



5 **7** Needs Action

Pin Type: General

Categories:


Landscape Misc

Location:

Created by:

 Mike Silverstein
Senior Construction Inspector

Sep 13, 2024 at 9:08 am EST



Notes:

Mike Silverstein September 13, 2024 9:08 AM EST

Animal burrow found on pond bank - Consult with environmental on animal species (possible gopher tortoise) or if active.

Photos:



Sep 12, 2024 at 3:58 pm EST



Sep 12, 2024 at 3:58 pm EST



Sep 12, 2024 at 3:58 pm EST

5

7

Needs Action *(continued)*

Created by:



Mike Silverstein
Senior Construction Inspector

Pin Type: General

Sep 13, 2024 at 9:08 am EST

Photos:



Sep 12, 2024 at 3:58 pm EST



Sep 12, 2024 at 3:58 pm EST



8

Observation

Pin Type: General

Categories:

Drainage


Location:

Created by:



Ryan Morgan
CEI Field Technician

Sep 16, 2024 at 8:35 am EST



Notes:

Ryan Morgan September 16, 2024 8:35 AM EST

Structure operating as designed.

Photos:



7

11

Needs Action

Created by:



Ryan Morgan
CEI Field Technician


Sep 13, 2024 at 9:18 am EST

Pin Type: General

Categories:

- Drainage
- Storm


Location:



Notes:

Ryan Morgan September 13, 2024 9:18 AM EST
Possible clog at both curb inlets, storm water staging up into gutter and roadway.

Photos:



Sep 13, 2024 at 9:18 am EST

8

13

Needs Action

Created by:



Mike Silverstein
Senior Construction Inspector


Sep 13, 2024 at 9:28 am EST

Pin Type: General

Categories:

- Landscape
- Misc

Location:



Notes:

Mike Silverstein September 13, 2024 9:28 AM EST

Animal burrow - Consult with environmental on animal species (possible gopher tortoise) - Mentioned in Item #7.

Photos:



Sep 13, 2024 at 9:20 am EST



20

Observation

Pin Type: General

Categories:

- Drainage
- Storm


Location:

Created by:



Ryan Morgan
CEI Field Technician

Sep 17, 2024 at 4:28 pm EST



Notes:

Ryan Morgan September 17, 2024 4:28 PM EST

Structure is functioning as designed.

Photos:



Sep 17, 2024 at 4:28 pm EST



Sep 17, 2024 at 4:28 pm EST



Sep 17, 2024 at 4:28 pm EST