Reserve Study Update Double Branch CDD Orange Park, Florida



Prepared for FY 2022 Report Date: May 9, 2022





May 9, 2022

Ms. Marilee Giles, Operations Manager Governmental Management Services 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Double Branch CDD

Dear Ms. Giles:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA. Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

CRShamand

Charles R. Sheppard *RS PRA CCI* Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275

www.communityadvisors.comm









SPECIAL NOTICE

THIS RESERVE ANALYLSIS INCLUDED A VISUAL OBSERVATION OF MAJOR COMPONENTS FOR YOUR PROPERTY. NO DISTRUCTION TESTING OR OTHER TESTING WAS CONDUCTED TO DETERMINE COMPONENT CONDITION. OUR ANALYSIS INCLUDES COMPONENTS WITH REPLACEMENT COST AND USEFUL LIFE PROJECTIONS THAT ARE TYPICAL FOR THIS TYPE OF FACILITY.

THIS ANALYSIS IS NOT A SAFETY INSPECTION OR STRUCTURAL INSPECTION AND WE RECOMMEND THE ASSOCIATION CONDUCT THOSE INSPECTIONS ON A REGULAR BASIS WITH OTHER CONSULTANTS.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Executive Summary	1-1
Financial Summary - Recommended Funding Plan	1-2
Recommended Funding Plan VS Fully Funded	1-3
Funding Assessment Comparison Chart	1-4
CURRENT FUNDING PLAN	
Financial Summary - Recommended Funding Plan	2-1
Current Funding Plan Chart	2-2
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	4-24
COMPONENT INVENTORY	
Component Inventory	5-1
Component Detail Index	5-8
Component Detail	5-15
DISCLOSURERS & INFORMATION	
Report Navigation	6-1
Important Information	6-2
Methodology & Information	6-4
Terms of Service	6-5

Executive Summary

Account Information

Account Name Double Branch CDD Account Number 1801

City Orange Park Last Site Visit April, 6 2022 State Florida Report Date May, 9 2022

In Service Date June, 15 2003 Report Version 1

Total Units Fiscal Year Start October, 1 2022
Study Level Level II Update Fiscal year End September, 30 2023

Reserve Fund Information

Current Component Replacement Cost \$2,859,449
Number of Components 198
Reserve Fund Beginning Balance \$1,325,474

Billing Term

Annually

Component Funding (Straight Line)

Recommended First Year Reserve Fund Contribution \$176,789
Interest Rate on Reserve Deposits 0%
Inflation Rate on Replacement Cost 0%

Pooled Cash (Current Funding Plan)

Current Year Reserve Fund Contribution \$8,250
Interest Rate on Reserve Deposits Variable
Inflation Rate on Replacement Cost Variable
Annual Contribution Increases 3.0%

Pooled Cash (Recommended Funding Plan)

Recommended First Year Reserve Fund Contribution
Interest Rate on Reserve Deposits
Inflation Rate on Replacement Cost
Annual Contribution Increases

\$170,912
Variable
Variable
3.0%


Comments

- Current funding level is not adequate for future component replacement in FY 2029.
- Recommended funding plan requires larger contributions for adequate funding.


Double Branch CDD Financial Summary - Recommended Funding Plan

Begining Balance: \$1,325,474 Fully Funded: \$2,000,849 Tax Rate:0%

				. 62			4	©	>	Ø
	estal	. ₁ 07	స్థా చి	gija . R	ی د	چ.	red ritio	र देवे ह	रही स्वीत	Se Go
Year	Police St. Charles	A Solicio de Solicio d	A Collins of the Coll	Operations	And Die	S. Andrews	TO THE	A ST	20 Can 20	Si Signi
22-23	2,859,449	6.0%	170,912	0	0.50%	4,629	570,670	930,344	1,683,563	55%
23-24	3,031,016	5.0%	176,912	0	1.00%	10,305	75,896	1,040,792	1,865,281	56%
24-25	3,182,567	4.0%	181,320	0	1.50%	16,992	89,307	1,149,797	2,031,678	57%
25-26	3,309,869	3.0%	186,760	0	2.00%	25,022	85,467	1,276,112	2,195,262	58%
26-27	3,409,165	3.0%	192,362	0	2.50%	29,952	270,401	1,228,025	2,180,883	56%
27-28	3,511,440	3.0%	198,133	0	3.00%	38,651	137,776	1,327,034	2,309,263	57%
28-29	3,616,784	3.0%	204,077	0	3.50%	46,464	203,581	1,373,994	2,381,653	58%
29-30	3,725,287	3.0%	210,200	0	3.50%	38,689	478,806	1,144,076	2,179,861	52%
30-31	3,837,046	3.0%	216,506	0	3.50%	39,984	218,192	1,182,374	2,247,610	53%
31-32	3,952,157	3.0%	223,001	0	3.50%	44,409	136,555	1,313,228	2,408,417	55%
32-33	4,070,722	3.0%	229,691	0	3.50%	18,025	1,027,929	533,015	1,663,042	32%
33-34	4,192,843	3.0%	236,582	0	3.50%	25,160	50,734	744,022	1,909,049	39%
34-35	4,318,629	3.0%	243,679	0	3.50%	28,060	185,978	829,783	2,030,587	41%
35-36	4,448,188	3.0%	250,989	0	3.50%	30,197	217,997	892,973	2,130,467	42%
36-37	4,581,633	3.0%	258,519	0	3.50%	38,695	45,908	1,144,279	2,418,498	47%
37-38	4,719,082	3.0%	266,275	0	3.50%	19,058	866,036	563,576	1,878,582	30%
38-39	4,860,655	3.0%	274,263	0	3.50%	23,131	176,955	684,014	2,040,608	34%
39-40	5,006,474	3.0%	282,491	0	3.50%	29,973	110,129	886,350	2,284,964	39%
40-41	5,156,669	3.0%	290,965	0	3.50%	36,098	145,940	1,067,473	2,508,662	43%
41-42	5,311,369	3.0%	299,694	0	3.50%	44,938	83,215	1,328,891	2,812,841	47%
42-43	5,470,710	3.0%	308,685	0	3.50%	45,056	350,250	1,332,382	2,860,539	47%
43-44	5,634,831	3.0%	317,946	0	3.50%	54,575	91,042	1,613,861	3,186,374	51%
44-45	5,803,876	3.0%	327,484	0	3.50%	47,161	593,879	1,394,627	3,014,076	46%
45-46	5,977,992	3.0%	337,309	0	3.50%	54,235	182,376	1,603,794	3,270,770	49%
46-47	6,157,332	3.0%	347,428	0	3.50%	47,168	603,578	1,394,812	3,111,952	45%
47-48	6,342,052	3.0%	357,851	0	3.50%	53,782	216,048	1,590,396	3,358,467	47%
48-49	6,532,313	3.0%	368,586	0	3.50%	57,434	317,998	1,698,419	3,518,640	48%
49-50	6,728,283	3.0%	379,644	0	3.50%	68,079	132,944	2,013,198	3,885,832	52%
50-51	6,930,131	3.0%	391,033	0	3.50%	68,026	460,630	2,011,627	3,938,480	51%
51-52	7,138,035	3.0%	402,764	0	3.50%	75,513	256,886	2,233,018	4,214,880	53%




The recommended funding plan provides adequate funding with moderate contributions over time.



Double Branch CDD Financial Summary - Recommended Funding Plan

Begining Balance: \$1,325,474 Fully Funded: \$2,000,849 Tax Rate:0%

	0	U	. , ,		•	. , ,				
	officit	æ	~ .0	idor	, x	χ.	, S (Š	is a s	ر الله الله الله الله الله الله الله الل	چگ ریک یوا
Year	A SE CO.	THE SECTION OF THE SE	THE SOLUTION OF THE SOLUTION O	Ozloj Trodij	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	~ 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Rio A di	A Spirit S	76 Fig. 76	Sp And S
			0.470		0.50-1					
22-23	2,859,449	6.0%	8,250	0	0.50%	3,815	570,670	766,869	1,683,563	46%
23-24	3,031,016	5.0%	8,498	0	1.00%	6,995	75,896	706,465	1,865,281	38%
24-25	3,182,567	4.0%	8,752	0	1.50%	9,389	89,307	635,299	2,031,678	31%
25-26	3,309,869	3.0%	9,015	0	2.00%	11,177	85,467	570,025	2,195,262	26%
26-27	3,409,165	3.0%	9,285	0	2.50%	7,723	270,401	316,632	2,180,883	15%
27-28	3,511,440	3.0%	9,564	0	3.00%	5,653	137,776	194,073	2,309,263	8%
28-29	3,616,784	3.0%	9,851	0	3.50%	12	203,581	355	2,381,653	0%
29-30	3,725,287	3.0%	10,146	0	3.50%		478,806	-468,305	2,179,861	
30-31	3,837,046	3.0%	10,451	0	3.50%		218,192	-676,045	2,247,610	
31-32	3,952,157	3.0%	10,764	0	3.50%		136,555	-801,836	2,408,417	
32-33	4,070,722	3.0%	11,087	0	3.50%		1,027,929	-1,818,678	1,663,042	
33-34	4,192,843	3.0%	11,420	0	3.50%		50,734	-1,857,992	1,909,049	
34-35	4,318,629	3.0%	11,763	0	3.50%		185,978	-2,032,208	2,030,587	
35-36	4,448,188	3.0%	12,115	0	3.50%		217,997	-2,238,090	2,130,467	
36-37	4,581,633	3.0%	12,479	0	3.50%		45,908	-2,271,519	2,418,498	
37-38	4,719,082	3.0%	12,853	0	3.50%		866,036	-3,124,702	1,878,582	
38-39	4,860,655	3.0%	13,239	0	3.50%		176,955	-3,288,418	2,040,608	
39-40	5,006,474	3.0%	13,636	0	3.50%		110,129	-3,384,911	2,284,964	
40-41	5,156,669	3.0%	14,045	0	3.50%		145,940	-3,516,806	2,508,662	
41-42	5,311,369	3.0%	14,466	0	3.50%		83,215	-3,585,555	2,812,841	
42-43	5,470,710	3.0%	14,900	0	3.50%		350,250	-3,920,905	2,860,539	
43-44	5,634,831	3.0%	15,347	0	3.50%		91,042	-3,996,599	3,186,374	
44-45	5,803,876	3.0%	15,808	0	3.50%		593,879	-4,574,670	3,014,076	
45-46	5,977,992	3.0%	16,282	0	3.50%		182,376	-4,740,765	3,270,770	
46-47	6,157,332	3.0%	16,771	0	3.50%		603,578	-5,327,572	3,111,952	
47-48	6,342,052	3.0%	17,274	0	3.50%		216,048	-5,526,347	3,358,467	
48-49	6,532,313	3.0%	17,792	0	3.50%		317,998	-5,826,552	3,518,640	
49-50	6,728,283	3.0%	18,326	0	3.50%		132,944	-5,941,171	3,885,832	
50-51	6,930,131	3.0%	18,875	0	3.50%		460,630	-6,382,926	3,938,480	
51-52	7,138,035	3.0%	19,442	0	3.50%		256,886	-6,620,371	4,214,880	



	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Beginning Balance	1,325,474	930,344	1,040,792	1,149,797	1,276,112	1,228,025	1,327,034	1,373,994	1,144,076	1,182,374
Annual Assessment	170,912	176,039	181,320	186,760	192,362	198,133	204,077	210,200	216,506	223,001
Interest Earned	4,629	10,305	16,992	25,022	29,952	38,651	46,464	38,689	39,984	44,409
Expenditures	570,670	75,896	89,307	85,467	270,401	137,776	203,581	478,806	218,192	136,555
Fully Funded Reserves	1,683,563	1,865,281	2,031,678	2,195,262	2,180,883	2,309,263	2,381,653	2,179,861	2,247,610	2,408,417
Percent Fully Funded	55%	56%	57%	58%	56%	57%	58%	52%	53%	55%
Ending Balance	930,344	1,040,792	1,149,797	1,276,112	1,228,025	1,327,034	1,373,994	1,144,076	1,182,374	1,313,228
Description										
Site Components - General										
Alumnium Flag Pole										
Fountain Replacement Allowance - East Pond					5,961					
Irrigation Pump 1	6,300				,					
Irrigation Pump 2		6,678								
Irrigation System Repair Allowance	3,000					3,684				
Site Components - General Total:	9,300	6,678			5,961	3,684				
Site Components - Monuments & Signage										
Entry Sign Refurbishment - Cannons Point								4,951		
Entry Sign Refurbishment - Fall Creek								4,951		
Entry Sign Refurbishment - Natures Hammock								4,951		
Entry Sign Refurbishment - Oakleaf								20,454		
Entry Sign Refurbishment - Silverleaf								4,951		
Entry Sign Refurbishment - The Oaks								4,951		
Entry Sign Refurbishment - Timberfield								4,951		
Entry Sign Refurbishment Allowance - Amenity	12,000									
Refurbishment Allowance - Brick Columns								7,035		
Standing Seam Roof - Amenity Entry Feature										
Site Components - Monuments & Signage Total:	12,000							57,193		
Site Components - Fencing										
Vinyl Privacy Fence - Oakleaf Village Parkway										
Vinyl Privacy Fence - Plantation Oaks Blvd.										
Vinyl Ranch Fence - Oakleaf Village Parkway										

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Site Components - Fencing continued										
Vinyl Ranch Fence - Plantation Oaks Blvd. Lot										
Site Components - Fencing Total:										
Site Components - Parking Lots										
Asphalt Mil/Overlay - Amenity Lot					118,247					
Asphalt Mill/Overlay - P.O.B. Lot					85,627					
Asphalt Mill/Overlay - P.O.B. Lot (New)										
Concrete Paver Replacement - Amenity Lot										
Decorative Light Poles - Amenity Lot						17,683				
Dumpster Enclosure Gates						4,912				
Site Concrete Replacement Allowance			11,130							
Site Components - Parking Lots Total:			11,130		203,874	22,595				
Site Components - Bridges & Bulkheads										
Pedestrian East Bridge Painting										
Pedestrian Nature Walk Bridge Painting										5,529
Pedestrian South West Bridge Painting										
Pedestrian West Bridge Painting										
Wood Bulkhead - East Bridge									21,964	
Wood Bulkhead - OVP Pond									39,934	
Wood Bulkhead - SouthWest Bridge									23,295	
Wood Bulkhead - West Bridge									24,626	
Site Components - Bridges & Bulkheads Total:									109,820	5,529
Site Components - Sport Field										
Asphalt Replacement (4 Phases of Replacement)							13,600			
Decorative Light Poles			38,065							
Light Bollards			6,678							
Outdoor Fitness Equip. Allowance										
Park Benches	10,400									
Picnic Tables	9,000									
Site Components - Sport Field Total:	19,400		44,743				13,600			

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description	22 23	20 24	24 25	25 20	20 27	27 20	20 27	27 50	30 31	31 32
Clubhouse - General										
Access Control Panel								4,951		
Brick Tuck Point & Seal Allowance	15,500							,		
Ceiling Fans - Exterior	5,600									
Exterior Trim Paint	16,400									
Interior Painting				5,325						
Office Furniture Allowance			1,113							
Security Camera System Allowance		10,600								
Vinyl Ceiling/Trim										
Water Coolers										5,805
Wood Pergola - Ext Porch						13,754				
Clubhouse - General Total:	37,500	10,600	1,113	5,325		13,754		4,951		5,805
Club House - Roofing										
Concrete Tiles/Underlayment										
Standing Seam Metal Roof										
Club House - Roofing Total:										
Clubhouse - Locker Rooms										
Refurbishment Allowance							145,711			
Clubhouse - Locker Rooms Total:							145,711			
Clubhouse - Club Room & Kitchen										
Electric Range					1,908					
Floor Tile - Club Room					1,500				36,840	
Floor Tile - Kitchen									1,437	
Furniture Allowance - Club Room	3,000								,	
Refrigerator	- ,				1,431					
Vinyl Flooring - Offices					,					
Wood Cabinet & Laminate Top - Kitchen						8,633				
Wood Cabinets & Stone Top - Club Room										
Wood Credenza & Stone Top - Club Room										
Clubhouse - Club Room & Kitchen Total:	3,000				3,338	8,633			38,277	

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Clubhouse - Mechanical Systems										
HVAC - Clubhouse West Wing	21,600									
HVAC Unit - Club Room	9,000									
Clubhouse - Mechanical Systems Total:	30,600									
Field House										
Concrete Tiles/Underlayment										
Exterior Painting	4,400									
Park Bench		5,512								
Picnic Table		2,756								
Refurbishment Allowance - Restrooms	18,000									
Standing Seam Metal Roof										
Vinyl Ceiling/Trim Water Coolers										
Field House Total:	22,400	8,268								
rieiu mouse totai.	22,400	0,200								
Fitness Center										
Aluminium Fence										
Asphalt Shinge Roof										26,758
Carpet Tiles - Strength Room			7,613							
Coffee Bar Cabinets & Top						2,456				
Exterior Painting	7,200									
Fitness Equipment Annual Allowance	3,000	3,180	3,339	3,473	3,577	3,684	3,795	3,908	4,026	4,146
Floor Tile - Lobby										17,691
HVAC System		19,080					,			
Interior Painting							6,324			2.215
Reception Desk Cabinets										3,317
Reception Desk Solid Surface Top										5,307
Refurbishment Allowance - Restrooms							7.500			53,074
Water Cooler - ADA Bi-Level							7,589			2,488
Wood Flooring Refinishing - Cardio Room Fitness Center Total:	10.200	22.260	10.052	2 472	2 577	6 140	17 700	2 000	4.026	
rithess Center Iotal:	10,200	22,260	10,952	3,473	3,577	6,140	17,708	3,908	4,026	112,783

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Basketball Courts										
Basketball Poles & Goals								9,380		
Chain Link Fence								16,034		
Court Resurfacing				8,589				,	9,957	
Light Poles								15,634		
Basketball Courts Total:				8,589				41,047	9,957	
Tennis Courts										
Chain Link Fence - 10 Ft								31,259		
Chain Link Fence - 4 Ft								5,628		
Court Resurfacing				21,780					25,249	
Light Poles								31,267		
Shade Structures			8,681							
Tennis Courts Total:			8,681	21,780				68,155	25,249	
Swimming Pool - General										
Aluminium Fence										
Lane Divider Reel						2,382				
Lane Dividers	3,640									
Lifeguard Chairs		2,968								
Pool Furniture Replacement Allowance					47,690					
Pool Lift			7,123							
Pool Play Equipment Allowance	7 000	7.2 00		40,513	7 0 6 4	< 1.10	c 22.4	1	< 5 00	
Pool Pumps & Equipment Annual Allowance	5,000	5,300	5,565	5,788	5,961	6,140	6,324	6,514	6,709	6,911
Pool Resurfacing/Tile		0.00	40.00	46.204	-2 (-1	0.500	< 22.4	297,038	< =00	
Swimming Pool - General Total:	8,640	8,268	12,688	46,301	53,651	8,522	6,324	303,552	6,709	6,911
Pool House										
Asphalt Shingles	7,920									
Exterior Painting	7,000									
Refurbishment Allowance - Restrooms Standing Seam Metal Roof	6,200									
Pool House Total:	21,120									

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Pool Shade Structures										
Exterior Painting - Pavilion										5,529
Standing Seam Metal Roof - Pavilion										·
Wood Pergola Replacement						44,012				
Pool Shade Structures Total:						44,012				5,529
Pool Slide & Tower										
Aluminium Railings - Pool Slide Tower						12,575				
Pool Slide Refurbishment Allowance							20,238			
Pool Slide Tower Painting		12,720								
Shade Structures - Pool Side Tower									24,154	
Standing Seam Metal Roof - Slide Tower										
Pool Slide & Tower Total:		12,720				12,575	20,238		24,154	
Park - Fall Creek										
Bi-pod Swing Set - Two Bay	3,200									
Gazebo Roof										
Park Benches -Back to Back	2,300									
Picnic Table	2,600									
Plastic Play Surface Border	6,090									
Play Equipment Allowance	50,000									
Vinyl Ranch Fence										
Park - Fall Creek Total:	64,190									
Park - Natures Hammock										
Bi-pod Swing Set - Two Bay										
Fence/Gates - Dog Park										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border										
Play Equipment Allowance										
Scoop Digger										
Vinyl Ranch Fence										
Park - Natures Hammock Total:										

Community Advisors Page 3-6 May 9, 2022

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description			-		-					
Park - Timberfield										
Bi-pod Swing Set - Two Bay	3,200									
Gazebo Roof	-,									
Park Benches -Back to Back	2,300									
Picnic Table	2,600									
Plastic Play Surface Border	6,930									
Play Equipment Allowance	30,000									
Vinyl Ranch Fence										
Park - Timberfield Total:	45,030									
Park - Stonebrier										
Bi-pod Swing Set - Two Bay	3,200									
Gazebo Roof	,									
Park Benches -Back to Back		2,438								
Picnic Table	2,600									
Plastic Play Surface Border	5,460									
Play Equipment Allowance	30,000									
Scoop Digger	2,100									
Spring Rider	1,600									
Vinyl Ranch Fence						17,860				
Park - Stonebrier Total:	44,960	2,438				17,860				
Park - Worthngton Oaks										
Bi-pod Swing Set - Two Bay	3,200									
Gazebo Roof										
Park Benches -Back to Back	2,300									
Picnic Table	2,600									
Plastic Play Surface Border	6,510									
Play Equipment Allowance	30,000									
Vinyl Ranch Fence										
Park - Worthngton Oaks Total:	44,610									

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Park - Oakbrook										
Gazebo Roof										
Park Bench	1,300									
Picnic Table	1,300									
Park - Oakbrook Total:	2,600									
Park - Silverleaf										
Bi-pod Swing Set - Two Bay	3,200									
Gazebo Roof										
Park Benches -Back to Back		2,438								
Picnic Table	2,600									
Plastic Play Surface Border	5,250									
Play Equipment Allowance										
Vinyl Ranch Fence										
Park - Silverleaf Total:	11,050	2,438								
Park - Club House										
Bi-Pod Swing Set One Bay	2,200									
Bi-Pod Swing Set Two Bay	3,200									
Park Benches	10,400									
Play Equipment	30,000									
Scoop Digger	2,100									
Spring Rider	4,800									
Park - Club House Total:	52,700									
Park - Sport Field										
Play Equipment Allowance - Playground	30,000									
Scoop Digger - Playground	2,100									
Spring Rider - Playground	1,600									
Park - Sport Field Total:	33,700									
Park - The Oaks										
Bi-pod Swing Set - Two Bay	3,200									
Gazebo Roof										

	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32
Description										
Park - The Oaks continued										
Park Benches	1,300									
Picnic Table	2,600									
Plastic Play Surface Border	5,460									
Play Equipment Allowance	30,000									
Vinyl Ranch Fence										
Park - The Oaks Total:	42,560									
Park - Cannons Point										
Bi-pod Swing Set - Two Bay	3,200									
Cresent Climber	2,800									
Gazebo Roof										
Park Benches -Back to Back	2,300									
Picnic Table	2,600									
Plastic Play Surface Border	6,510									
Play Equipment Allowance	30,000									
Scoop Digger	2,100									
Spring Rider	1,600									
Vinyl Ranch Fence										
Park - Cannons Point Total:	51,110									
Operating Expense										
Ice Machine - Club Romm	Unfunded									
Metal Trash Cans	Unfunded									
Wood Repair/Painting - Pool Pergola	Unfunded									
Components Not Included										
Cardio Room Wood Floor Replacement	Unfunded									
Glass Display Refrigerator	v	2,226								
Ice Machine	4,000									
Pool Slide Replacement	Unfunded									
Components Not Included Total:	4,000	2,226								
Year Total:	570,670	75,896	89,307	85,467	270,401	137,776	203,581	478,806	218,192	136,555

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Beginning Balance	1,313,228	533,015	744,022	829,783	892,973	1,144,279	563,576	684,014	886,350	1,067,473
Annual Assessment	229,691	236,582	243,679	250,989	258,519	266,275	274,263	282,491	290,965	299,694
Interest Earned	18,025	25,160	28,060	30,197	38,695	19,058	23,131	29,973	36,098	44,938
Expenditures	1,027,929	50,734	185,978	217,997	45,908	866,036	176,955	110,129	145,940	83,215
Fully Funded Reserves	1,663,042	1,909,049	2,030,587	2,130,467	2,418,498	1,878,582	2,040,608	2,284,964	2,508,662	2,812,841
Percent Fully Funded	32%	39%	41%	42%	47%	30%	34%	39%	43%	47%
Ending Balance	533,015	744,022	829,783	892,973	1,144,279	563,576	684,014	886,350	1,067,473	1,328,891
Description										
Site Components - General										
Alumnium Flag Pole	4,983									
Fountain Replacement Allowance - East Pond			7,552							
Irrigation Pump 1			9,515							
Irrigation Pump 2				9,800						
Irrigation System Repair Allowance	4,271					4,951				
Site Components - General Total:	9,253		17,066	9,800		4,951				
Site Components - Monuments & Signage										
Entry Sign Refurbishment - Cannons Point								6,653		
Entry Sign Refurbishment - Fall Creek								6,653		
Entry Sign Refurbishment - Natures Hammock								6,653		
Entry Sign Refurbishment - Oakleaf								27,488		
Entry Sign Refurbishment - Silverleaf								6,653		
Entry Sign Refurbishment - The Oaks								6,653		
Entry Sign Refurbishment - Timberfield								6,653		
Entry Sign Refurbishment Allowance - Amenity	17,083							0.455		
Refurbishment Allowance - Brick Columns						4.000		9,455		
Standing Seam Roof - Amenity Entry Feature	4= 000					4,390				
Site Components - Monuments & Signage Total:	17,083					4,390		76,862		
Site Components - Fencing										
Vinyl Privacy Fence - Oakleaf Village Parkway	350,087									
Vinyl Privacy Fence - Plantation Oaks Blvd.	132,839									
Vinyl Ranch Fence - Oakleaf Village Parkway	54,461									

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Site Components - Fencing continued										
Vinyl Ranch Fence - Plantation Oaks Blvd. Lot	28,905									
Site Components - Fencing Total:	566,292									
Site Components - Parking Lots										
Asphalt Mil/Overlay - Amenity Lot										
Asphalt Mill/Overlay - P.O.B. Lot										
Asphalt Mill/Overlay - P.O.B. Lot (New)									64,759	
Concrete Paver Replacement - Amenity Lot	124,145									
Decorative Light Poles - Amenity Lot										
Dumpster Enclosure Gates										
Site Concrete Replacement Allowance			15,103							
Site Components - Parking Lots Total:	124,145		15,103						64,759	
Site Components - Bridges & Bulkheads										
Pedestrian East Bridge Painting	5,694									
Pedestrian Nature Walk Bridge Painting										
Pedestrian South West Bridge Painting	5,694									
Pedestrian West Bridge Painting	5,694									
Wood Bulkhead - East Bridge										
Wood Bulkhead - OVP Pond										
Wood Bulkhead - SouthWest Bridge										
Wood Bulkhead - West Bridge	15 002									
Site Components - Bridges & Bulkheads Total:	17,083									
Site Components - Sport Field										
Asphalt Replacement (4 Phases of Replacement)					17,228					
Decorative Light Poles										
Light Bollards										
Outdoor Fitness Equip. Allowance										49,037
Park Benches							17,679			
Picnic Tables					1= 446		15,299			40.00=
Site Components - Sport Field Total:					17,228		32,977			49,037

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description	0_00					0.00		0, 10		
Clubhouse - General										
Access Control Panel										
Brick Tuck Point & Seal Allowance										
Ceiling Fans - Exterior							9,519			
Exterior Trim Paint			24,769							
Interior Painting		6,745								8,544
Office Furniture Allowance										
Security Camera System Allowance		14,663								
Vinyl Ceiling/Trim	15,717									
Water Coolers										
Wood Pergola - Ext Porch										
Clubhouse - General Total:	15,717	21,408	24,769				9,519			8,544
Club House - Roofing										
Concrete Tiles/Underlayment						187,842				
Standing Seam Metal Roof						15,843				
Club House - Roofing Total:						203,686				
Clubhouse - Locker Rooms										
Refurbishment Allowance										
Clubhouse - Locker Rooms Total:										
Clubhouse - Club Room & Kitchen										
Electric Range							2,720			
Floor Tile - Club Room							2,720			
Floor Tile - Kitchen										
Furniture Allowance - Club Room										
Refrigerator							2,040			
Vinyl Flooring - Offices									3,787	
Wood Cabinet & Laminate Top - Kitchen										
Wood Cabinets & Stone Top - Club Room	8,542									
Wood Credenza & Stone Top - Club Room	4,100									
Clubhouse - Club Room & Kitchen Total:	12,642						4,760		3,787	

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Clubhouse - Mechanical Systems										
HVAC - Clubhouse West Wing			32,623							
HVAC Unit - Club Room			13,593							
Clubhouse - Mechanical Systems Total:			46,215							
Field House										
Concrete Tiles/Underlayment						23,448				
Exterior Painting	6,264									
Park Bench							8,839			
Picnic Table							4,420			
Refurbishment Allowance - Restrooms										
Standing Seam Metal Roof						31,687				
Vinyl Ceiling/Trim	11,787									
Water Coolers				6,534						
Field House Total:	18,051			6,534		55,135	13,259			
Fitness Center										
Aluminium Fence	12,300									
Asphalt Shinge Roof										
Carpet Tiles - Strength Room			10,330							
Coffee Bar Cabinets & Top										
Exterior Painting	10,250									
Fitness Equipment Annual Allowance	4,271	4,399	4,531	4,667	4,807	4,951	5,100	5,253	5,410	5,572
Floor Tile - Lobby										
HVAC System				28,001						
Interior Painting					8,011					
Reception Desk Cabinets										
Reception Desk Solid Surface Top										
Refurbishment Allowance - Restrooms										
Water Cooler - ADA Bi-Level										2 242
Wood Flooring Refinishing - Cardio Room Fitness Center Total:	26 921	4.200	14061	22.669	12 010	4.051	<i>5</i> 100	E 252	<i>E 4</i> 10	3,343
runess Center Iotal:	26,821	4,399	14,861	32,668	12,818	4,951	5,100	5,253	5,410	8,916

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Basketball Courts										
Basketball Poles & Goals										
Chain Link Fence										
Court Resurfacing				11,543					13,381	
Light Poles										
Basketball Courts Total:				11,543					13,381	
Tennis Courts										
Chain Link Fence - 10 Ft										
Chain Link Fence - 4 Ft										
Court Resurfacing				29,270					33,932	
Light Poles										
Shade Structures										
Tennis Courts Total:				29,270					33,932	
Swimming Pool - General										
Aluminium Fence	44,075									
Lane Divider Reel										
Lane Dividers	5,182									
Lifeguard Chairs			10.11.				4,760			
Pool Furniture Replacement Allowance Pool Lift			60,412					11,205		
Pool Play Equipment Allowance								,		
Pool Pumps & Equipment Annual Allowance	7,118	7,332	7,552	7,778	8,011	8,252	8,499	8,754	9,017	9,287
Pool Resurfacing/Tile										
Swimming Pool - General Total:	56,375	7,332	67,964	7,778	8,011	8,252	13,259	19,960	9,017	9,287
Pool House										
Asphalt Shingles										
Exterior Painting	9,965									
Refurbishment Allowance - Restrooms										
Standing Seam Metal Roof						2,641				
Pool House Total:	9,965					2,641				

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Pool Shade Structures										
Exterior Painting - Pavilion										7,430
Standing Seam Metal Roof - Pavilion						43,886				, , , ,
Wood Pergola Replacement						,				
Pool Shade Structures Total:						43,886				7,430
Pool Slide & Tower										
Aluminium Railings - Pool Slide Tower										
Pool Slide Refurbishment Allowance							27,198			
Pool Slide Tower Painting		17,596					.,			
Shade Structures - Pool Side Tower		,								
Standing Seam Metal Roof - Slide Tower						10,562				
Pool Slide & Tower Total:		17,596				10,562	27,198			
Park - Fall Creek										
Bi-pod Swing Set - Two Bay						5,281				
Gazebo Roof	6,833					-, -				
Park Benches -Back to Back	,						3,910			
Picnic Table							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						82,517				
Vinyl Ranch Fence	18,860									
Park - Fall Creek Total:	25,693					87,798	8,329			
Park - Natures Hammock										
Bi-pod Swing Set - Two Bay				4,978						
Fence/Gates - Dog Park						16,305				
Gazebo Roof	6,833									
Park Benches -Back to Back					3,685					
Picnic Table					4,166					
Plastic Play Surface Border									10,604	
Play Equipment Allowance				46,668						
Scoop Digger				3,267						
Vinyl Ranch Fence	7,927									
Park - Natures Hammock Total:	14,760			54,913	7,851	16,305			10,604	

Community Advisors Page 3-15 May 9, 2022

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Park - Timberfield										
Bi-pod Swing Set - Two Bay						5,281				
Gazebo Roof	5,296					,				
Park Benches -Back to Back							3,910			
Picnic Table							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Vinyl Ranch Fence	18,928									
Park - Timberfield Total:	24,224					54,792	8,329			
Park - Stonebrier										
Bi-pod Swing Set - Two Bay						5,281				
Gazebo Roof	6,833					-, -				
Park Benches -Back to Back								4,027		
Picnic Table							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Scoop Digger						3,466				
Spring Rider						2,641				
Vinyl Ranch Fence										
Park - Stonebrier Total:	6,833					60,898	4,420	4,027		
Park - Worthngton Oaks										
Bi-pod Swing Set - Two Bay						5,281				
Gazebo Roof	6,833									
Park Benches -Back to Back							3,910			
Picnic Table							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Vinyl Ranch Fence	14,008									
Park - Worthngton Oaks Total:	20,842					54,792	8,329			

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Park - Oakbrook										
Gazebo Roof	6,833									
Park Bench							2,210			
Picnic Table							2,210			
Park - Oakbrook Total:	6,833						4,420			
Park - Silverleaf										
Bi-pod Swing Set - Two Bay						5,281				
Gazebo Roof	6,833									
Park Benches -Back to Back							4.420	4,027		
Picnic Table							4,420			
Plastic Play Surface Border Play Equipment Allowance				62,224						
Vinyl Ranch Fence	15,512			02,224						
Park - Silverleaf Total:	22,345			62,224		5,281	4,420	4,027		
D. I. Cl. I II				·-, ·		-,	-,	-,		
Park - Club House						2 (21				
Bi-Pod Swing Set One Bay Bi-Pod Swing Set Two Bay						3,631 5,281				
Park Benches						3,201	17,679			
Play Equipment						49,510	17,077			
Scoop Digger						3,466				
Spring Rider						7,922				
Park - Club House Total:						69,810	17,679			
Park - Sport Field										
Play Equipment Allowance - Playground						49,510				
Scoop Digger - Playground						3,466				
Spring Rider - Playground						2,641				
Park - Sport Field Total:						55,617				
Park - The Oaks										
Bi-pod Swing Set - Two Bay						5,281				
Gazebo Roof	6,833					,				

	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42
Description										
Park - The Oaks continued										
Park Benches							2,210			
Picnic Table							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Vinyl Ranch Fence	6,833									
Park - The Oaks Total:	13,667					54,792	6,629			
Park - Cannons Point										
Bi-pod Swing Set - Two Bay						5,281				
Cresent Climber									5,049	
Gazebo Roof	6,833									
Park Benches -Back to Back							3,910			
Picnic Table							4,420			
Plastic Play Surface Border										
Play Equipment Allowance						49,510				
Scoop Digger						3,466				
Spring Rider	10 471					2,641				
Vinyl Ranch Fence	12,471					60.000	0.220		7.040	
Park - Cannons Point Total:	19,304					60,898	8,329		5,049	
Operating Expense										
Ice Machine - Club Romm	Unfunded									
Metal Trash Cans	Unfunded									
Wood Repair/Painting - Pool Pergola	Unfunded									
Components Not Included										
Cardio Room Wood Floor Replacement	Unfunded									
Glass Display Refrigerator				3,267						
Ice Machine						6,601				
Pool Slide Replacement	Unfunded									
Components Not Included Total:				3,267		6,601				
Year Total:	1,027,929	50,734	185,978	217,997	45,908	866,036	176,955	110,129	145,940	83,215

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Beginning Balance	1,328,891	1,332,382	1,613,861	1,394,627	1,603,794	1,394,812	1,590,396	1,698,419	2,013,198	2,011,627
Annual Assessment	308,685	317,946	327,484	337,309	347,428	357,851	368,586	379,644	391,033	402,764
Interest Earned	45,056	54,575	47,161	54,235	47,168	53,782	57,434	68,079	68,026	75,513
Expenditures	350,250	91,042	593,879	182,376	603,578	216,048	317,998	132,944	460,630	256,886
Fully Funded Reserves	2,860,539	3,186,374	3,014,076	3,270,770	3,111,952	3,358,467	3,518,640	3,885,832	3,938,480	4,214,880
Percent Fully Funded	47%	51%	46%	49%	45%	47%	48%	52%	51%	53%
Ending Balance	1,332,382	1,613,861	1,394,627	1,603,794	1,394,812	1,590,396	1,698,419	2,013,198	2,011,627	2,233,018
Description										
Site Components - General										
Alumnium Flag Pole										
Fountain Replacement Allowance - East Pond	9,566								12,118	
Irrigation Pump 1					13,566					
Irrigation Pump 2						13,973				
Irrigation System Repair Allowance	5,740					6,654				
Site Components - General Total:	15,306				13,566	20,627			12,118	
Site Components - Monuments & Signage										
Entry Sign Refurbishment - Cannons Point								8,941		
Entry Sign Refurbishment - Fall Creek								8,941		
Entry Sign Refurbishment - Natures Hammock								8,941		
Entry Sign Refurbishment - Oakleaf								36,942		
Entry Sign Refurbishment - Silverleaf								8,941		
Entry Sign Refurbishment - The Oaks								8,941		
Entry Sign Refurbishment - Timberfield								8,941		
Entry Sign Refurbishment Allowance - Amenity	22,958									
Refurbishment Allowance - Brick Columns								12,706		
Standing Seam Roof - Amenity Entry Feature										
Site Components - Monuments & Signage Total:	22,958							103,297		
Site Components - Fencing										
Vinyl Privacy Fence - Oakleaf Village Parkway										
Vinyl Privacy Fence - Plantation Oaks Blvd.										
Vinyl Ranch Fence - Oakleaf Village Parkway										

Community Advisors Page 3-19 May 9, 2022

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Site Components - Fencing continued										
Vinyl Ranch Fence - Plantation Oaks Blvd. Lot										
Site Components - Fencing Total:										
Site Components - Parking Lots										
Asphalt Mil/Overlay - Amenity Lot					213,567					
Asphalt Mill/Overlay - P.O.B. Lot					154,652					
Asphalt Mill/Overlay - P.O.B. Lot (New)										
Concrete Paver Replacement - Amenity Lot										
Decorative Light Poles - Amenity Lot										
Dumpster Enclosure Gates						8,872				
Site Concrete Replacement Allowance			20,297							
Site Components - Parking Lots Total:			20,297		368,219	8,872				
Site Components - Bridges & Bulkheads										
Pedestrian East Bridge Painting			8,119							
Pedestrian Nature Walk Bridge Painting		7,882								
Pedestrian South West Bridge Painting			8,119							
Pedestrian West Bridge Painting			8,119							
Wood Bulkhead - East Bridge										
Wood Bulkhead - OVP Pond										
Wood Bulkhead - SouthWest Bridge										
Wood Bulkhead - West Bridge										
Site Components - Bridges & Bulkheads Total:		7,882	24,357							
Site Components - Sport Field										
Asphalt Replacement (4 Phases of Replacement)			21,824							
Decorative Light Poles					73,644					
Light Bollards					12,920					
Outdoor Fitness Equip. Allowance										
Park Benches										
Picnic Tables										
Site Components - Sport Field Total:			21,824		86,564					

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description	12 13	10 11	44 45	45 40	40 47	47 40	40 42	42 50	20 21	01 02
Clubhouse - General										
Access Control Panel			7,713							
Brick Tuck Point & Seal Allowance	29,655		7,710							
Ceiling Fans - Exterior	,									
Exterior Trim Paint					35,315					
Interior Painting								10,824		
Office Furniture Allowance			2,030							
Security Camera System Allowance		19,706								
Vinyl Ceiling/Trim										
Water Coolers		8,277								
Wood Pergola - Ext Porch	_					24,841				
Clubhouse - General Total:	29,655	27,983	9,743		35,315	24,841		10,824		
Club House - Roofing										
Concrete Tiles/Underlayment										
Standing Seam Metal Roof										
Club House - Roofing Total:										
Clubhouse - Locker Rooms										
Refurbishment Allowance							263,170			
Clubhouse - Locker Rooms Total:							263,170			
Clubhouse - Club Room & Kitchen										
Electric Range									3,878	
Floor Tile - Club Room									66,537	
Floor Tile - Kitchen									2,596	
Furniture Allowance - Club Room	5,740									
Refrigerator									2,908	
Vinyl Flooring - Offices										
Wood Cabinet & Laminate Top - Kitchen						15,592				
Wood Cabinets & Stone Top - Club Room										
Wood Credenza & Stone Top - Club Room										
Clubhouse - Club Room & Kitchen Total:	5,740					15,592			75,919	

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Clubhouse - Mechanical Systems										
HVAC - Clubhouse West Wing					46,512					
HVAC Unit - Club Room					19,380					
Clubhouse - Mechanical Systems Total:					65,892					
Field House										
Concrete Tiles/Underlayment										
Exterior Painting	8,418									
Park Bench										
Picnic Table										
Refurbishment Allowance - Restrooms	34,438									
Standing Seam Metal Roof										
Vinyl Ceiling/Trim										
Water Coolers									10,179	
Field House Total:	42,856								10,179	
Fitness Center										
Aluminium Fence										
Asphalt Shinge Roof										48,328
Carpet Tiles - Strength Room			13,883							
Coffee Bar Cabinets & Top		3,941								
Exterior Painting	13,775									
Fitness Equipment Annual Allowance	5,740	5,912	6,089	6,272	6,460	6,654	6,853	7,059	7,271	7,489
Floor Tile - Lobby										31,953
HVAC System						39,923				
Interior Painting			10,149							
Reception Desk Cabinets										5,991
Reception Desk Solid Surface Top										9,586
Refurbishment Allowance - Restrooms										95,858
Water Cooler - ADA Bi-Level		11,824								
Wood Flooring Refinishing - Cardio Room										4,493
Fitness Center Total:	19,515	21,677	30,121	6,272	6,460	46,576	6,853	7,059	7,271	203,698

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Basketball Courts										
Basketball Poles & Goals			14,614							
Chain Link Fence										30,722
Court Resurfacing				15,512					17,983	
Light Poles										
Basketball Courts Total:			14,614	15,512					17,983	30,722
Tennis Courts										
Chain Link Fence - 10 Ft										
Chain Link Fence - 4 Ft										
Court Resurfacing				39,337					45,602	
Light Poles										
Shade Structures					16,796					
Tennis Courts Total:				39,337	16,796				45,602	
Swimming Pool - General										
Aluminium Fence										
Lane Divider Reel						4,303				
Lane Dividers	6,964									
Lifeguard Chairs										
Pool Furniture Replacement Allowance Pool Lift	76,528								96,944	
Pool Lift Pool Play Equipment Allowance				73,171						
Pool Pumps & Equipment Annual Allowance	9,566	9,853	10,149	10,453	10,767	11,090	11,422	11,765	12,118	12,481
Pool Resurfacing/Tile	9,500	7,033	462,776	10,433	10,707	11,090	11,422	11,703	12,110	12,461
Swimming Pool - General Total:	93,058	9,853	472,924	83,624	10,767	15,392	11,422	11,765	109,062	12,481
	20,000	,,,,,,	· · - , · - ·	55,521	20,7.07	10,0>2	,	22,. 00	207,002	12,101
Pool House										
Asphalt Shingles	15,153									
Exterior Painting	13,392									
Refurbishment Allowance - Restrooms Standing Seam Metal Roof	11,862									
Pool House Total:	40,407									

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description	42-43	45-44	77-75	45-40	40-47	47-40	40-42	47-50	30-31	31-32
Pool Shade Structures										
Exterior Painting - Pavilion										9,985
Standing Seam Metal Roof - Pavilion										7,703
Wood Pergola Replacement						79,491				
Pool Shade Structures Total:						79,491				9,985
Pool Slide & Tower										
Aluminium Railings - Pool Slide Tower										
Pool Slide Refurbishment Allowance							36,551			
Pool Slide Tower Painting		23,647								
Shade Structures - Pool Side Tower				37,631						
Standing Seam Metal Roof - Slide Tower										
Pool Slide & Tower Total:		23,647		37,631			36,551			
Park - Fall Creek										
Bi-pod Swing Set - Two Bay										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border	11,651									
Play Equipment Allowance										
Vinyl Ranch Fence	44 684									
Park - Fall Creek Total:	11,651									
Park - Natures Hammock										
Bi-pod Swing Set - Two Bay									7,755	
Fence/Gates - Dog Park										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border									70 700	
Play Equipment Allowance									72,708	
Scoop Digger									5,090	
Vinyl Ranch Fence									05.553	
Park - Natures Hammock Total:									85,553	

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Park - Timberfield										
Bi-pod Swing Set - Two Bay										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border	13,259									
Play Equipment Allowance										
Vinyl Ranch Fence										
Park - Timberfield Total:	13,259									
Park - Stonebrier										
Bi-pod Swing Set - Two Bay										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border	10,446									
Play Equipment Allowance										
Scoop Digger										
Spring Rider Vinyl Ranch Fence										
Park - Stonebrier Total:	10,446									
	10,440									
Park - Worthngton Oaks										
Bi-pod Swing Set - Two Bay										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border	12,455									
Play Equipment Allowance										
Vinyl Ranch Fence Park - Worthngton Oaks Total:	12.455									
rark - worthington Oaks Iotai:	12,455									

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Park - Oakbrook										
Gazebo Roof										
Park Bench										
Picnic Table										
Park - Oakbrook Total:										
Park - Silverleaf										
Bi-pod Swing Set - Two Bay										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table	10.044									
Plastic Play Surface Border Play Equipment Allowance	10,044								96,944	
Vinyl Ranch Fence									70,7 44	
Park - Silverleaf Total:	10,044								96,944	
Park - Club House Bi-Pod Swing Set One Bay Bi-Pod Swing Set Two Bay Park Benches Play Equipment Scoop Digger Spring Rider Park - Club House Total:										
Park - Sport Field Play Equipment Allowance - Playground										
Scoop Digger - Playground										
Spring Rider - Playground										
Park - Sport Field Total:										
Park - The Oaks										
Bi-pod Swing Set - Two Bay										
Gazebo Roof										

Double Branch CDD Income & Expense Spreadsheet

	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52
Description										
Park - The Oaks continued										
Park Benches										
Picnic Table										
Plastic Play Surface Border	10,446									
Play Equipment Allowance										
Vinyl Ranch Fence										
Park - The Oaks Total:	10,446									
Park - Cannons Point										
Bi-pod Swing Set - Two Bay										
Cresent Climber										
Gazebo Roof										
Park Benches -Back to Back										
Picnic Table										
Plastic Play Surface Border	12,455									
Play Equipment Allowance										
Scoop Digger										
Spring Rider										
Vinyl Ranch Fence Park - Cannons Point Total:	10.455									
Park - Cannons Point Total:	12,455									
Operating Expense										
Ice Machine - Club Romm	Unfunded									
Metal Trash Cans	Unfunded									
Wood Repair/Painting - Pool Pergola	Unfunded									
Components Not Included										
Cardio Room Wood Floor Replacement	Unfunded									
Glass Display Refrigerator	- Organiaea					4,658				
Ice Machine						.,000				
Pool Slide Replacement	Unfunded									
Components Not Included Total:						4,658				
Year Total:	350,250	91,042	593,879	182,376	603,578	216,048	317,998	132,944	460,630	256,886

Description	Expenditures
Replacement Year 22-23	
Site Components - General	
Irrigation Pump 1	6,300
Irrigation System Repair Allowance	3,000
Site Components - Monuments & Signage	
Entry Sign Refurbishment Allowance - Amenity	12,000
Site Components - Sport Field	
Park Benches	10,400
Picnic Tables	9,000
Clubhouse - General	
Brick Tuck Point & Seal Allowance	15,500
Ceiling Fans - Exterior	5,600
Exterior Trim Paint	16,400
Clubhouse - Club Room & Kitchen	
Furniture Allowance - Club Room	3,000
Clubhouse - Mechanical Systems	
HVAC - Clubhouse West Wing	21,600
HVAC Unit - Club Room	9,000
Field House	
Exterior Painting	4,400
Refurbishment Allowance - Restrooms	18,000
Fitness Center	
Exterior Painting	7,200
Fitness Equipment Annual Allowance	3,000
Swimming Pool - General	
Lane Dividers	3,640
Pool Pumps & Equipment Annual Allowance	5,000
Pool House	
Asphalt Shingles	7,920
Exterior Painting	7,000
Refurbishment Allowance - Restrooms	6,200
Park - Fall Creek	
Bi-pod Swing Set - Two Bay	3,200
Park Benches -Back to Back	2,300
Picnic Table	2,600

Description	Expenditures
Replacement Year 22-23 continued	
Plastic Play Surface Border	6,090
Play Equipment Allowance	50,000
Park - Timberfield	
Bi-pod Swing Set - Two Bay	3,200
Park Benches -Back to Back	2,300
Picnic Table	2,600
Plastic Play Surface Border	6,930
Play Equipment Allowance	30,000
Park - Stonebrier	
Bi-pod Swing Set - Two Bay	3,200
Picnic Table	2,600
Plastic Play Surface Border	5,460
Play Equipment Allowance	30,000
Scoop Digger	2,100
Spring Rider	1,600
Park - Worthngton Oaks	
Bi-pod Swing Set - Two Bay	3,200
Park Benches -Back to Back	2,300
Picnic Table	2,600
Plastic Play Surface Border	6,510
Play Equipment Allowance	30,000
Park - Oakbrook	
Park Bench	1,300
Picnic Table	1,300
Park - Silverleaf	
Bi-pod Swing Set - Two Bay	3,200
Picnic Table	2,600
Plastic Play Surface Border	5,250
Park - Club House	
Bi-Pod Swing Set One Bay	2,200
Bi-Pod Swing Set Two Bay	3,200
Park Benches	10,400
Play Equipment	30,000
Scoop Digger	2,100
Spring Rider	4,800

Description	Expenditures
Replacement Year 22-23 continued	
Park - Sport Field	
Play Equipment Allowance - Playground	30,000
Scoop Digger - Playground	2,100
Spring Rider - Playground	1,600
Park - The Oaks	
Bi-pod Swing Set - Two Bay	3,200
Park Benches	1,300
Picnic Table	2,600
Plastic Play Surface Border	5,460
Play Equipment Allowance	30,000
Park - Cannons Point	
Bi-pod Swing Set - Two Bay	3,200
Cresent Climber	2,800
Park Benches -Back to Back	2,300
Picnic Table	2,600
Plastic Play Surface Border	6,510
Play Equipment Allowance	30,000
Scoop Digger	2,100
Spring Rider	1,600
Components Not Included	
Ice Machine	4,000
Total for 2022 - 2023	\$570,670
Replacement Year 23-24	
Site Components - General	
Irrigation Pump 2	6,678
Clubhouse - General	
Security Camera System Allowance	10,600
Field House	
Park Bench	5,512
Picnic Table	2,756
Fitness Center	,
Fitness Equipment Annual Allowance	3,180
HVAC System	19,080
· · · · · · · · · · · · · · · · · · ·	,

Description	Expenditures
Replacement Year 23-24 continued	
Swimming Pool - General	
Lifeguard Chairs	2,968
Pool Pumps & Equipment Annual Allowance	5,300
Pool Slide & Tower	
Pool Slide Tower Painting	12,720
Park - Stonebrier	
Park Benches -Back to Back	2,438
Park - Silverleaf	
Park Benches -Back to Back	2,438
Components Not Included	
Glass Display Refrigerator	2,226
Total for 2023 - 2024	\$75,896
Replacement Year 24-25	
Site Components - Parking Lots	
Site Concrete Replacement Allowance	11,130
Site Components - Sport Field	
Decorative Light Poles	38,065
Light Bollards	6,678
Clubhouse - General	
Office Furniture Allowance	1,113
Fitness Center	
Carpet Tiles - Strength Room	7,613
Fitness Equipment Annual Allowance	3,339
Tennis Courts	
Shade Structures	8,681
Swimming Pool - General	
Pool Lift	7,123
Pool Pumps & Equipment Annual Allowance	5,565
Total for 2024 - 2025	\$89,307
Replacement Year 25-26	
Clubhouse - General	
Interior Painting	5,325

Description	Expenditures
Replacement Year 25-26 continued	
Fitness Center	
Fitness Equipment Annual Allowance	3,473
Basketball Courts	
Court Resurfacing	8,589
Tennis Courts	
Court Resurfacing	21,780
Swimming Pool - General	
Pool Play Equipment Allowance	40,513
Pool Pumps & Equipment Annual Allowance	5,788
Total for 2025 - 2026	\$85,467
Replacement Year 26-27	
Site Components - General	
Fountain Replacement Allowance - East Pond	5,961
Site Components - Parking Lots	
Asphalt Mil/Overlay - Amenity Lot	118,247
Asphalt Mill/Overlay - P.O.B. Lot	85,627
Clubhouse - Club Room & Kitchen	
Electric Range	1,908
Refrigerator	1,431
Fitness Center	
Fitness Equipment Annual Allowance	3,577
Swimming Pool - General	
Pool Furniture Replacement Allowance	47,690
Pool Pumps & Equipment Annual Allowance	5,961
Total for 2026 - 2027	\$270,401
Replacement Year 27-28	
Site Components - General	
Irrigation System Repair Allowance	3,684
Site Components - Parking Lots	
Decorative Light Poles - Amenity Lot	17,683
Dumpster Enclosure Gates	4,912

Description	Expenditures
Replacement Year 27-28 continued	
Clubhouse - General	
Wood Pergola - Ext Porch	13,754
Clubhouse - Club Room & Kitchen	
Wood Cabinet & Laminate Top - Kitchen	8,633
Fitness Center	
Coffee Bar Cabinets & Top	2,456
Fitness Equipment Annual Allowance	3,684
Swimming Pool - General	
Lane Divider Reel	2,382
Pool Pumps & Equipment Annual Allowance	6,140
Pool Shade Structures	
Wood Pergola Replacement	44,012
Pool Slide & Tower	
Aluminium Railings - Pool Slide Tower	12,575
Park - Stonebrier	4=0.40
Vinyl Ranch Fence	17,860
Total for 2027 - 2028	\$137,776
Replacement Year 28-29	
Site Components - Sport Field	
Asphalt Replacement (4 Phases of Replacement)	13,600
Clubhouse - Locker Rooms	
Refurbishment Allowance	145,711
Fitness Center	
Fitness Equipment Annual Allowance	3,795
Interior Painting	6,324
Water Cooler - ADA Bi-Level	7,589
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	6,324
Pool Slide & Tower	••
Pool Slide Refurbishment Allowance	20,238
Total for 2028 - 2029	\$203,581

Description	Expenditures
Replacement Year 29-30	
Site Components - Monuments & Signage	
Entry Sign Refurbishment - Cannons Point	4,951
Entry Sign Refurbishment - Fall Creek	4,951
Entry Sign Refurbishment - Natures Hammock	4,951
Entry Sign Refurbishment - Oakleaf	20,454
Entry Sign Refurbishment - Silverleaf	4,951
Entry Sign Refurbishment - The Oaks	4,951
Entry Sign Refurbishment - Timberfield	4,951
Refurbishment Allowance - Brick Columns	7,035
Clubhouse - General	
Access Control Panel	4,951
Fitness Center	
Fitness Equipment Annual Allowance	3,908
Basketball Courts	
Basketball Poles & Goals	9,380
Chain Link Fence	16,034
Light Poles	15,634
Tennis Courts	
Chain Link Fence - 10 Ft	31,259
Chain Link Fence - 4 Ft	5,628
Light Poles	31,267
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	6,514
Pool Resurfacing/Tile	297,038
Total for 2029 - 2030	\$478,806
D. 1	
Replacement Year 30-31	
Site Components - Bridges & Bulkheads	
Wood Bulkhead - East Bridge	21,964
Wood Bulkhead - OVP Pond	39,934
Wood Bulkhead - SouthWest Bridge	23,295
Wood Bulkhead - West Bridge	24,626
Clubhouse - Club Room & Kitchen	
Floor Tile - Club Room	36,840

Description	Expenditures
Replacement Year 30-31 continued Floor Tile - Kitchen	1,437
Fitness Center Fitness Equipment Annual Allowance	4,026
Basketball Courts Court Resurfacing	9,957
Tennis Courts Court Resurfacing	25,249
Swimming Pool - General Pool Pumps & Equipment Annual Allowance	6,709
Pool Slide & Tower Shade Structures - Pool Side Tower	24,154
Total for 2030 - 2031	\$218,192
Replacement Year 31-32	
Site Components - Bridges & Bulkheads Pedestrian Nature Walk Bridge Painting	5,529
Clubhouse - General Water Coolers	5,805
Fitness Center	26.750
Asphalt Shinge Roof Fitness Equipment Annual Allowance	26,758 4,146
Floor Tile - Lobby	17,691
Reception Desk Cabinets	3,317
Reception Desk Solid Surface Top	5,307
Refurbishment Allowance - Restrooms	53,074
Wood Flooring Refinishing - Cardio Room	2,488
Swimming Pool - General	C 011
Pool Pumps & Equipment Annual Allowance	6,911
Pool Shade Structures Exterior Painting - Pavilion	5,529
Total for 2031 - 2032	\$136,555
Replacement Year 32-33	
Site Components - General	
Alumnium Flag Pole	4,983

Description	Expenditures
Replacement Year 32-33 continued	
Irrigation System Repair Allowance	4,271
Site Components - Monuments & Signage Entry Sign Refurbishment Allowance - Amenity	17,083
Site Components - Fencing	
Vinyl Privacy Fence - Oakleaf Village Parkway	350,087
Vinyl Privacy Fence - Plantation Oaks Blvd.	132,839
Vinyl Ranch Fence - Oakleaf Village Parkway	54,461
Vinyl Ranch Fence - Plantation Oaks Blvd. Lot	28,905
Site Components - Parking Lots	
Concrete Paver Replacement - Amenity Lot	124,145
Site Components - Bridges & Bulkheads	
Pedestrian East Bridge Painting	5,694
Pedestrian South West Bridge Painting	5,694
Pedestrian West Bridge Painting	5,694
Clubhouse - General	
Vinyl Ceiling/Trim	15,717
Clubhouse - Club Room & Kitchen	
Wood Cabinets & Stone Top - Club Room	8,542
Wood Credenza & Stone Top - Club Room	4,100
Field House	
Exterior Painting	6,264
Vinyl Ceiling/Trim	11,787
Fitness Center	
Aluminium Fence	12,300
Exterior Painting	10,250
Fitness Equipment Annual Allowance	4,271
Swimming Pool - General	
Aluminium Fence	44,075
Lane Dividers	5,182
Pool Pumps & Equipment Annual Allowance	7,118
Pool House	
Exterior Painting	9,965
Park - Fall Creek	
Gazebo Roof	6,833

Description	Expenditures
Replacement Year 32-33 continued	
Vinyl Ranch Fence	18,860
Park - Natures Hammock	
Gazebo Roof	6,833
Vinyl Ranch Fence	7,927
Park - Timberfield	
Gazebo Roof	5,296
Vinyl Ranch Fence	18,928
Park - Stonebrier	
Gazebo Roof	6,833
Park - Worthngton Oaks	
Gazebo Roof	6,833
Vinyl Ranch Fence	14,008
Park - Oakbrook	
Gazebo Roof	6,833
Park - Silverleaf	
Gazebo Roof	6,833
Vinyl Ranch Fence	15,512
Park - The Oaks	< 0.22
Gazebo Roof	6,833
Vinyl Ranch Fence	6,833
Park - Cannons Point	6 022
Gazebo Roof	6,833
Vinyl Ranch Fence	12,471
Total for 2032 - 2033	\$1,027,929
Replacement Year 33-34	
Clubhouse - General	
Interior Painting	6,745
Security Camera System Allowance	14,663
Fitness Center	
Fitness Equipment Annual Allowance	4,399
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	7,332

Description	Expenditures
Replacement Year 33-34 continued	
Pool Slide & Tower	
Pool Slide Tower Painting	17,596
Total for 2033 - 2034	\$50,734
Replacement Year 34-35	
Site Components - General	
Fountain Replacement Allowance - East Pond	7,552
Irrigation Pump 1	9,515
Site Components - Parking Lots	
Site Concrete Replacement Allowance	15,103
Clubhouse - General	
Exterior Trim Paint	24,769
Clubhouse - Mechanical Systems	
HVAC - Clubhouse West Wing	32,623
HVAC Unit - Club Room	13,593
Fitness Center	
Carpet Tiles - Strength Room	10,330
Fitness Equipment Annual Allowance	4,531
Swimming Pool - General	
Pool Furniture Replacement Allowance	60,412
Pool Pumps & Equipment Annual Allowance	7,552
Total for 2034 - 2035	\$185,978
Replacement Year 35-36	
Site Components - General	
Irrigation Pump 2	9,800
Field House	
Water Coolers	6,534
Fitness Center	
Fitness Equipment Annual Allowance	4,667
HVAC System	28,001
Basketball Courts	
Court Resurfacing	11,543

Description	Expenditures
Replacement Year 35-36 continued	
Tennis Courts	
Court Resurfacing	29,270
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	7,778
Park - Natures Hammock	
Bi-pod Swing Set - Two Bay	4,978
Play Equipment Allowance	46,668
Scoop Digger	3,267
Park - Silverleaf	
Play Equipment Allowance	62,224
Components Not Included	
Glass Display Refrigerator	3,267
Total for 2035 - 2036	\$217,997
Replacement Year 36-37	
Site Components - Sport Field	
Asphalt Replacement (4 Phases of Replacement)	17,228
Fitness Center	
Fitness Equipment Annual Allowance	4,807
Interior Painting	8,011
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	8,011
Park - Natures Hammock	
Park Benches -Back to Back	3,685
Picnic Table	4,166
Total for 2036 - 2037	\$45,908
Replacement Year 37-38	
Site Components - General	
Irrigation System Repair Allowance	4,951
Site Components - Monuments & Signage	
Standing Seam Roof - Amenity Entry Feature	4,390
Club House - Roofing	
Concrete Tiles/Underlayment	187,842

Description	Expenditures
Replacement Year 37-38 continued	
Standing Seam Metal Roof	15,843
Field House	
Concrete Tiles/Underlayment	23,448
Standing Seam Metal Roof	31,687
Fitness Center Fitness Equipment Annual Allowance	4,951
Swimming Pool - General	7,731
Pool Pumps & Equipment Annual Allowance	8,252
Pool House	0,252
Standing Seam Metal Roof	2,641
Pool Shade Structures	
Standing Seam Metal Roof - Pavilion	43,886
Pool Slide & Tower	
Standing Seam Metal Roof - Slide Tower	10,562
Park - Fall Creek	
Bi-pod Swing Set - Two Bay	5,281
Play Equipment Allowance	82,517
Park - Natures Hammock	
Fence/Gates - Dog Park	16,305
Park - Timberfield	
Bi-pod Swing Set - Two Bay	5,281
Play Equipment Allowance	49,510
Park - Stonebrier	7.2 01
Bi-pod Swing Set - Two Bay	5,281
Play Equipment Allowance	49,510 3,466
Scoop Digger Spring Rider	2,641
Park - Worthngton Oaks	2,011
Bi-pod Swing Set - Two Bay	5,281
Play Equipment Allowance	49,510
Park - Silverleaf	
Bi-pod Swing Set - Two Bay	5,281
Park - Club House	
Bi-Pod Swing Set One Bay	3,631

Description	Expenditures
Replacement Year 37-38 continued	
Bi-Pod Swing Set Two Bay	5,281
Play Equipment	49,510
Scoop Digger	3,466
Spring Rider	7,922
Park - Sport Field	
Play Equipment Allowance - Playground	49,510
Scoop Digger - Playground	3,466
Spring Rider - Playground	2,641
Park - The Oaks	
Bi-pod Swing Set - Two Bay	5,281
Play Equipment Allowance	49,510
Park - Cannons Point	
Bi-pod Swing Set - Two Bay	5,281
Play Equipment Allowance	49,510
Scoop Digger	3,466
Spring Rider	2,641
Components Not Included	
Ice Machine	6,601
Total for 2037 - 2038	\$866,036
Replacement Year 38-39	
Site Components - Sport Field	
Park Benches	17,679
Picnic Tables	15,299
Clubhouse - General	
Ceiling Fans - Exterior	9,519
Clubhouse - Club Room & Kitchen	
Electric Range	2,720
Refrigerator	2,040
Field House	
Park Bench	8,839
Picnic Table	4,420
Fitness Center	
Fitness Equipment Annual Allowance	5,100

Description	Expenditures
Replacement Year 38-39 continued	
Swimming Pool - General	
Lifeguard Chairs	4,760
Pool Pumps & Equipment Annual Allowance	8,499
Pool Slide & Tower	
Pool Slide Refurbishment Allowance	27,198
Park - Fall Creek	
Park Benches -Back to Back	3,910
Picnic Table	4,420
Park - Timberfield	
Park Benches -Back to Back	3,910
Picnic Table	4,420
Park - Stonebrier	
Picnic Table	4,420
Park - Worthngton Oaks	
Park Benches -Back to Back	3,910
Picnic Table	4,420
Park - Oakbrook	
Park Bench	2,210
Picnic Table	2,210
Park - Silverleaf	
Picnic Table	4,420
Park - Club House	
Park Benches	17,679
Park - The Oaks	
Park Benches	2,210
Picnic Table	4,420
Park - Cannons Point	
Park Benches -Back to Back	3,910
Picnic Table	4,420
Total for 2038 - 2039	\$176,955
Replacement Year 39-40	
Site Components - Monuments & Signage	
Entry Sign Refurbishment - Cannons Point	6,653

Description	Expenditures
Replacement Year 39-40 continued	
Entry Sign Refurbishment - Fall Creek	6,653
Entry Sign Refurbishment - Natures Hammock	6,653
Entry Sign Refurbishment - Oakleaf	27,488
Entry Sign Refurbishment - Silverleaf	6,653
Entry Sign Refurbishment - The Oaks	6,653
Entry Sign Refurbishment - Timberfield	6,653
Refurbishment Allowance - Brick Columns	9,455
Fitness Center	
Fitness Equipment Annual Allowance	5,253
Swimming Pool - General	
Pool Lift	11,205
Pool Pumps & Equipment Annual Allowance	8,754
Park - Stonebrier	
Park Benches -Back to Back	4,027
Park - Silverleaf	
Park Benches -Back to Back	4,027
Total for 2039 - 2040	\$110,129
100011012007 2010	Ψ 11 0,1 2 >
Replacement Year 40-41	
Site Components - Parking Lots	
Asphalt Mill/Overlay - P.O.B. Lot (New)	64,759
Clubhouse - Club Room & Kitchen	
Vinyl Flooring - Offices	3,787
Fitness Center	
Fitness Equipment Annual Allowance	5,410
Basketball Courts	
Court Resurfacing	13,381
Tennis Courts	
Court Resurfacing	33,932
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	9,017
Park - Natures Hammock	
Plastic Play Surface Border	10,604
•	

Description	Expenditures
Replacement Year 40-41 continued	
Park - Cannons Point	
Cresent Climber	5,049
Total for 2040 - 2041	\$145,940
Replacement Year 41-42	
Site Components - Sport Field	
Outdoor Fitness Equip. Allowance	49,037
Clubhouse - General	0.544
Interior Painting	8,544
Fitness Center	5 570
Fitness Equipment Annual Allowance Wood Flooring Refinishing - Cardio Room	5,572 3,343
Swimming Pool - General	3,343
Pool Pumps & Equipment Annual Allowance	9,287
Pool Shade Structures), 2 0,
Exterior Painting - Pavilion	7,430
Total for 2041 - 2042	\$83,215
Replacement Year 42-43	
Site Components - General	
Fountain Replacement Allowance - East Pond	9,566
Irrigation System Repair Allowance	5,740
Site Components - Monuments & Signage Entry Sign Refurbishment Allowance - Amenity	22,958
Clubhouse - General	
Brick Tuck Point & Seal Allowance	29,655
Clubhouse - Club Room & Kitchen	
Furniture Allowance - Club Room	5,740
Field House	
Exterior Painting	8,418
Refurbishment Allowance - Restrooms	34,438
Fitness Center Enterior Pointing	12 775
Exterior Painting	13,775

Description	Expenditures
Replacement Year 42-43 continued	
Fitness Equipment Annual Allowance	5,740
Swimming Pool - General	
Lane Dividers	6,964
Pool Furniture Replacement Allowance	76,528
Pool Pumps & Equipment Annual Allowance	9,566
Pool House	15 152
Asphalt Shingles	15,153
Exterior Painting Refurbishment Allowance - Restrooms	13,392 11,862
Park - Fall Creek	11,002
Plastic Play Surface Border	11,651
Park - Timberfield	11,031
Plastic Play Surface Border	13,259
Park - Stonebrier	13,237
Plastic Play Surface Border	10,446
Park - Worthngton Oaks	10,110
Plastic Play Surface Border	12,455
Park - Silverleaf	
Plastic Play Surface Border	10,044
Park - The Oaks	
Plastic Play Surface Border	10,446
Park - Cannons Point	
Plastic Play Surface Border	12,455
Total for 2042 - 2043	\$350,250
Replacement Year 43-44	
Site Components - Bridges & Bulkheads	
Pedestrian Nature Walk Bridge Painting	7,882
Clubhouse - General	
Security Camera System Allowance	19,706
Water Coolers	8,277
Fitness Center	
Coffee Bar Cabinets & Top	3,941

Description	Expenditures
Replacement Year 43-44 continued	
Fitness Equipment Annual Allowance	5,912
Water Cooler - ADA Bi-Level	11,824
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	9,853
Pool Slide & Tower	
Pool Slide Tower Painting	23,647
Total for 2043 - 2044	\$91,042
Replacement Year 44-45	
Site Components - Parking Lots	
Site Concrete Replacement Allowance	20,297
Site Components - Bridges & Bulkheads	
Pedestrian East Bridge Painting	8,119
Pedestrian South West Bridge Painting	8,119
Pedestrian West Bridge Painting	8,119
Site Components - Sport Field	
Asphalt Replacement (4 Phases of Replacement)	21,824
Clubhouse - General	
Access Control Panel	7,713
Office Furniture Allowance	2,030
Fitness Center	
Carpet Tiles - Strength Room	13,883
Fitness Equipment Annual Allowance	6,089
Interior Painting	10,149
Basketball Courts	14 614
Basketball Poles & Goals	14,614
Swimming Pool - General	10 140
Pool Pumps & Equipment Annual Allowance Pool Resurfacing/Tile	10,149
	462,776
Total for 2044 - 2045	\$593,879
Replacement Year 45-46	
Fitness Center	
Fitness Equipment Annual Allowance	6,272

Description	Expenditures
Replacement Year 45-46 continued	
Basketball Courts	
Court Resurfacing	15,512
Tennis Courts	
Court Resurfacing	39,337
Swimming Pool - General	
Pool Play Equipment Allowance	73,171
Pool Pumps & Equipment Annual Allowance	10,453
Pool Slide & Tower	
Shade Structures - Pool Side Tower	37,631
Total for 2045 - 2046	\$182,376
Replacement Year 46-47	
Site Components - General	
Irrigation Pump 1	13,566
Site Components - Parking Lots	
Asphalt Mil/Overlay - Amenity Lot	213,567
Asphalt Mill/Overlay - P.O.B. Lot	154,652
Site Components - Sport Field	
Decorative Light Poles	73,644
Light Bollards	12,920
Clubhouse - General	
Exterior Trim Paint	35,315
Clubhouse - Mechanical Systems	
HVAC - Clubhouse West Wing	46,512
HVAC Unit - Club Room	19,380
Fitness Center	
Fitness Equipment Annual Allowance	6,460
Tennis Courts	4 4 70 0
Shade Structures	16,796
Swimming Pool - General	10.7.7
Pool Pumps & Equipment Annual Allowance	10,767
Total for 2046 - 2047	\$603,578

Description	Expenditures
Replacement Year 47-48	
Site Components - General	
Irrigation Pump 2	13,973
Irrigation System Repair Allowance	6,654
Site Components - Parking Lots	
Dumpster Enclosure Gates	8,872
Clubhouse - General	
Wood Pergola - Ext Porch	24,841
Clubhouse - Club Room & Kitchen	
Wood Cabinet & Laminate Top - Kitchen	15,592
Fitness Center	
Fitness Equipment Annual Allowance	6,654
HVAC System	39,923
Swimming Pool - General	
Lane Divider Reel	4,303
Pool Pumps & Equipment Annual Allowance	11,090
Pool Shade Structures	
Wood Pergola Replacement	79,491
Components Not Included	
Glass Display Refrigerator	4,658
Total for 2047 - 2048	\$216,048
Replacement Year 48-49	
Clubhouse - Locker Rooms	
Refurbishment Allowance	263,170
Fitness Center	
Fitness Equipment Annual Allowance	6,853
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	11,422
Pool Slide & Tower	
Pool Slide Refurbishment Allowance	36,551
Total for 2048 - 2049	\$317,998
Replacement Year 49-50	
Site Components - Monuments & Signage	
Entry Sign Refurbishment - Cannons Point	8,941


Description	Expenditures
Replacement Year 49-50 continued	
Entry Sign Refurbishment - Fall Creek	8,941
Entry Sign Refurbishment - Natures Hammock	8,941
Entry Sign Refurbishment - Oakleaf	36,942
Entry Sign Refurbishment - Silverleaf	8,941
Entry Sign Refurbishment - The Oaks	8,941
Entry Sign Refurbishment - Timberfield	8,941
Refurbishment Allowance - Brick Columns	12,706
Clubhouse - General	
Interior Painting	10,824
Fitness Center	
Fitness Equipment Annual Allowance	7,059
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	11,765
Total for 2049 - 2050	\$132,944
10tai 101 204) - 2030	Ψ132,777
Replacement Year 50-51	
Site Components - General	
Fountain Replacement Allowance - East Pond	12,118
Clubhouse - Club Room & Kitchen	
Electric Range	3,878
Floor Tile - Club Room	66,537
Floor Tile - Kitchen	2,596
Refrigerator	2,908
Field House	
Water Coolers	10,179
Fitness Center	
Fitness Equipment Annual Allowance	7,271
Basketball Courts	
Court Resurfacing	17,983
Tennis Courts	- 1,5 00
Court Resurfacing	45,602
	15,002
Swimming Pool - General Pool Furniture Replacement Allowance	96,944
Pool Pumps & Equipment Annual Allowance	12,118
1 0011 amps & Equipment / mindul / mowanec	12,110

Description	Expenditures
Replacement Year 50-51 continued	
Park - Natures Hammock	
Bi-pod Swing Set - Two Bay	7,755
Play Equipment Allowance	72,708
Scoop Digger	5,090
Park - Silverleaf	
Play Equipment Allowance	96,944
Total for 2050 - 2051	\$460,630
Replacement Year 51-52	
Fitness Center	
Asphalt Shinge Roof	48,328
Fitness Equipment Annual Allowance	7,489
Floor Tile - Lobby	31,953
Reception Desk Cabinets	5,991
Reception Desk Solid Surface Top	9,586
Refurbishment Allowance - Restrooms	95,858
Wood Flooring Refinishing - Cardio Room	4,493
Basketball Courts	
Chain Link Fence	30,722
Swimming Pool - General	
Pool Pumps & Equipment Annual Allowance	12,481
Pool Shade Structures	
Exterior Painting - Pavilion	9,985
Total for 2051 - 2052	\$256,886

Double Branch CDD

Orange Park, Florida

Asset Current Cost by Category



			eji.			&		
	Ough Son	ర్ట్ త్వే మార్ట్ మార్ట్ మా		<u>خ</u> نون		igit.	·& &	CHÎ CÔ
Description	ರ್ಷ್ಣ ಜ್ಯಾ	क्षेत्रय	3° 2°	A ₀ ;	\$ 500	Ziji ^s	عاملة للمعالمة	C20 C00
Site Components - General								
Alumnium Flag Pole	2003	32-33	30	0	10	1 Each	3,500.00	3,500
Fountain Replacement Allowance - East Por	nd2019	26-27	8	0	4	1 Each	5,000.00	5,000
Irrigation Pump 1	2003	22-23	12	0	0	15 HP	420.00	6,300
Irrigation Pump 2	2003	23-24	12	9	1	15 HP	420.00	6,300
Irrigation System Repair Allowance	2015	22-23	5	0	0	1 Lump Sum	3,000.00	3,000
Site Components - General - Total								\$24,100
Site Components - Monuments & S	Signage	7						
Entry Sign Refurbishment - Cannons Point	2020	29-30	10	0	7	1 Lump Sum	3,800.00	3,800
Entry Sign Refurbishment - Fall Creek	2020	29-30	10	0	7	1 Lump Sum	3,800.00	3,800
Entry Sign Refurbishment - Natures Hammo		29-30	10	0	7	1 Lump Sum	3,800.00	3,800
Entry Sign Refurbishment - Oakleaf	2020	29-30	10	0	7	1 Lump Sum	15,700.00	15,700
Entry Sign Refurbishment - Silverleaf	2020	29-30	10	0	7	1 Lump Sum	3,800.00	3,800
Entry Sign Refurbishment - The Oaks	2020	29-30	10	0	7	1 Each	3,800.00	3,800
Entry Sign Refurbishment - Timberfield	2020	29-30	10	0	7	1 Lump Sum	3,800.00	3,800
Entry Sign Refurbishment Allowance - Ame		22-23	10	0	0	1 Lump Sum	12,000.00	12,000
Refurbishment Allowance - Brick Columns	2020	29-30	10	0	7	1 Lump Sum	5,400.00	5,400
Standing Seam Roof - Amenity Entry Featur	e2003	37-38	35	0	15	140 Square Feet	19.00	2,660
Site Components - Monuments & Signag								\$58,560
Site Components - Fencing								
Vinyl Privacy Fence - Oakleaf Village Park	2003	32-33	30	0	10	6,831 Linear Feet	36.00	245,916
Vinyl Privacy Fence - Plantation Oaks Blvd.		32-33	30	0	10	2,592 Linear Feet	36.00	93,312
Vinyl Ranch Fence - Oakleaf Village Parkw.		32-33	30	0	10	1,594 Linear Feet	24.00	38,256
Vinyl Ranch Fence - Plantation Oaks Blvd.		32-33	30	0	10	846 Linear Feet	24.00	20,304
Site Components - Fencing - Total	2003	32-33	30	U	10	040 Emeai i eei	24.00	\$397,788
Site Components - Fenering - Total								Ψ371,700
Site Components - Parking Lots								
Asphalt Mil/Overlay - Amenity Lot	2003	26-27	20	4	4	5,800 Square Yards	17.10	99,180
Asphalt Mill/Overlay - P.O.B. Lot	2003	26-27	20	4	4	4,200 Square Yards	17.10	71,820
Asphalt Mill/Overlay - P.O.B. Lot (New)	2021	40-41	20	0	18	2,100 Square Yards	17.10	35,910
Concrete Paver Replacement - Amenity Lot	2003	32-33	30	0	10	10,700 Square Feet	8.15	87,205
Decorative Light Poles - Amenity Lot	2003	27-28	25	0	5	8 Each	1,800.00	14,400
Dumpster Enclosure Gates	2003	27-28	20	5	5	2 Each	2,000.00	4,000
Site Concrete Replacement Allowance	2015	24-25	10	0	2	1 Lump Sum	10,000.00	10,000
Site Components - Parking Lots - Total								\$322,515
Site Components - Bridges & Bulk	cheads							
Pedestrian East Bridge Painting	2021	32-33	12	0	10	1 Lump Sum	4,000.00	4,000
Pedestrian Nature Walk Bridge Painting	2020	31-32	12	0	9	1 Lump Sum	4,000.00	4,000
Pedestrian South West Bridge Painting	2021	32-33	12	0	10	1 Lump Sum	4,000.00	4,000
Pedestrian West Bridge Painting	2021	32-33	12	0	10	1 Lump Sum	4,000.00	4,000
Wood Bulkhead - East Bridge	2003	30-31	28	0	8	132 Linear Feet	124.00	16,368
Wood Bulkhead - OVP Pond	2003	30-31	28	0	8	240 Linear Feet	124.00	29,760

		- d	port		nen't	igio		X .
Description	Out Styl	50 76 Sp. 160	, ,		Side of the second	Jäll ^s	عفالم	Children Cost
Site Components - Bridges & Bulkheads co								
Wood Bulkhead - SouthWest Bridge	2003	30-31	28	0	8	140 Linear Feet	124.00	17,360
Wood Bulkhead - West Bridge	2003	30-31	28	0	8	148 Linear Feet	124.00	18,352
Site Components - Bridges & Bulkheads	s - Total							\$97,840
Site Components - Sport Field								
Asphalt Replacement (4 Phases of Replace.	. 2021	28-29	8	0	6	448 Square Yards	24.00	10,752
Decorative Light Poles	2003	24-25	22	0	2	19 Each	1,800.00	34,200
Light Bollards	2003	24-25	22	0	2	10 Each	600.00	6,000
Outdoor Fitness Equip. Allowance	2017	41-42	25	0	19	12 Units	2,200.00	26,400
Park Benches	2003	22-23	16	3	0	8 Each	1,300.00	10,400
Picnic Tables	2003	22-23	16	3	0	5 Each	1,800.00	9,000
Site Components - Sport Field - Total								\$96,752
Clubhouse - General								
Access Control Panel	2015	29-30	15	0	7	1 Lump Sum	3,800.00	3,800
Brick Tuck Point & Seal Allowance	2003	22-23	20	0	0	2,500 Stalls	6.20	15,500
Ceiling Fans - Exterior	2003	22-23	16	0	0	14 Each	400.00	5,600
Exterior Trim Paint	2003	22-23	12	0	0	1 Lump Sum	16,400.00	16,400
Interior Painting	2015	25-26	8	3	3	1 Lump Sum	4,600.00	4,600
Office Furniture Allowance	2003	24-25	20	2	2	1 Lump Sum	1,000.00	1,000
Security Camera System Allowance	2010	23-24	10	4	1	1 Lump Sum	10,000.00	10,000
Vinyl Ceiling/Trim	2003	32-33	30	0	10	1,600 Square Feet	6.90	11,040
Water Coolers	2020	31-32	12	0	9	2 Each	2,100.00	4,200
Wood Pergola - Ext Porch	2003	27-28	20	5	5	400 Square Feet	28.00	11,200
Clubhouse - General - Total								\$83,340
Club House - Roofing								
Concrete Tiles/Underlayment	2003	37-38	35	0	15	9,485 Square Feet	12.00	113,820
Standing Seam Metal Roof	2003	37-38	35	0	15	600 Square Feet	16.00	9,600
Club House - Roofing - Total								\$123,420
Clubhouse - Locker Rooms								
Refurbishment Allowance	2003	28-29	20	6	6	2,400 Square Feet	48.00	115,200
Clubhouse - Locker Rooms - Total								\$115,200
Clubhouse - Club Room & Kitchen	1							
Electric Range	2003	26-27	12	12	4	1 Each	1,600.00	1,600
Floor Tile - Club Room	2003	30-31	20	8	8	1,961 Square Feet	14.00	27,454
Floor Tile - Kitchen	2003	30-31	20	8	8	84 Square Feet	12.75	1,071
Furniture Allowance - Club Room	2003	22-23	20	0	0	1 Lump Sum	3,000.00	3,000
Refrigerator	2003	26-27	12	12	4	1 Each	1,200.00	1,200
Vinyl Flooring - Offices	2021	40-41	20	0	18	300 Square Feet	7.00	2,100
Wood Cabinet & Laminate Top - Kitchen	2003	27-28	20	5	5	38 Linear Feet	185.00	7,030
Wood Cabinets & Stone Top - Club Room	2003	32-33	25	5	10	20 Linear Feet	300.00	6,000

		4	gent		ent	:5°		
Description	One Sol	څې پر د د د د	, ip ⁽ **§		star de	Jilis Jilis	عرفية رويخ	CHI CO'S
-			~	*.	~	~		0 0
Clubhouse - Club Room & Kitchen continue Wood Credenza & Stone Top - Club Room Clubhouse - Club Room & Kitchen - Tota	2003	32-33	25	5	10	12 Linear Feet	240.00	2,880 \$52,335
Clubhouse - Mechanical Systems								
HVAC - Clubhouse West Wing	2003	22-23	12	0	0	12 Tons	1,800.00	21,600
HVAC Unit - Club Room	2003	22-23	12	0	0	5 Tons	1,800.00	9,000
Clubhouse - Mechanical Systems - Total								\$30,600
Field House								
Concrete Tiles/Underlayment	2003	37-38	35	0	15	1,184 Square Feet	12.00	14,208
Exterior Painting	2003	22-23	10	7	0	2,200 Square Feet	2.00	4,400
Park Bench	2003	23-24	15	6	1	4 Each	1,300.00	5,200
Picnic Table	2003	23-24	15	6	1	2 Each	1,300.00	2,600
Refurbishment Allowance - Restrooms	2003	22-23	20	-3	0	1 Lump Sum	18,000.00	18,000
Standing Seam Metal Roof	2003	37-38	35	0	15	1,200 Square Feet	16.00	19,200
Vinyl Ceiling/Trim	2003	32-33	30	0	10	1,200 Square Feet	6.90	8,280
Water Coolers	2021	35-36	15	0	13	2 Each	2,100.00	4,200
Field House - Total								\$76,088
Fitness Center								
Aluminium Fence	2003	32-33	30	0	10	240 Linear Feet	36.00	8,640
Asphalt Shinge Roof	2012	31-32	20	0	9	44 Squares	440.00	19,360
Carpet Tiles - Strength Room	2012	24-25	10	3	2	180 Square Yards	38.00	6,840
Coffee Bar Cabinets & Top	2012	27-28	16	0	5	1 Lump Sum	2,000.00	2,000
Exterior Painting	2012	22-23	10	0	0	3,600 Square Feet	2.00	7,200
Fitness Equipment Annual Allowance	2015	22-23	1	0	0	1 Lump Sum	3,000.00	3,000
Floor Tile - Lobby	2012	31-32	20	0	9	800 Square Feet	16.00	12,800
HVAC System	2012	23-24	12	0	1	10 Tons	1,800.00	18,000
Interior Painting	2021	28-29	8	0	6	1 Lump Sum	5,000.00	5,000
Reception Desk Cabinets	2012	31-32	20	0	9	10 Linear Feet	240.00	2,400
Reception Desk Solid Surface Top	2012	31-32	20	0	9	24 Linear Feet	160.00	3,840
Refurbishment Allowance - Restrooms	2012	31-32	20	0	9	600 Square Feet	64.00	38,400
Water Cooler - ADA Bi-Level	2012	28-29	15	2	6	1 Each	6,000.00	6,000
Wood Flooring Refinishing - Cardio Room Fitness Center - Total	2012	31-32	10	10	9	900 Square Feet	2.00	$\frac{1,800}{\$135,280}$
Basketball Courts		• • • • •			_			
Basketball Poles & Goals	2003	29-30	15	12	7	4 Each	1,800.00	7,200
Chain Link Fence	2003	29-30	22	5	7	397 Linear Feet	31.00	12,307
Court Resurfacing	2021	25-26	5	0	3	1,060 Square Yards	7.00	7,420
Light Poles	2003	29-30	25	2	7	4 Each	3,000.00	12,000 \$38,027
Basketball Courts - Total								\$38,927

		<u>,</u>	gegi		ejt.	. K ²⁰		
Description	Ogg chang	, e	గ స్ట్రాఫ్		State of the State	Dill's	ئۆنگەن ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ ئۇنگىلىشىنىڭ	Child Of
-		~ ~	~ ~	À.	*	\sim	\sim 0	0 0
Tennis Courts	2002	20.20	24	2	7	774 Linna East	21.00	22.004
Chain Link Fence - 10 Ft	2003	29-30 29-30	24	3	7	774 Linear Feet	31.00	23,994
Chain Link Fence - 4 Ft	2003 2021	29-30 25-26	24 5	3	7 3	240 Linear Feet	18.00 7.00	4,320 18,816
Court Resurfacing	2021	29-30	25	2	3 7	2,688 Square Yards 8 Each	3,000.00	24,000
Light Poles Shade Structures	2003	24-25	22	0	2	2 Each	3,900.00	
Tennis Courts - Total	2003	24-23	22	U	2	2 Each	3,900.00	\$78,930
Swimming Pool - General								
Aluminium Fence	2003	32-33	30	0	10	860 Linear Feet	36.00	30,960
Lane Divider Reel	2003	27-28	20	5	5	1 Each	1,940.00	1,940
Lane Dividers	2003	22-23	10	6	0	7 Lanes	520.00	3,640
Lifeguard Chairs	2003	23-24	15	6	1	2 Each	1,400.00	2,800
Pool Furniture Replacement Allowance	2019	26-27	8	0	4	1 Lump Sum	40,000.00	40,000
Pool Lift	2003	24-25	15	7	2	2 Each	3,200.00	6,400
Pool Play Equipment Allowance	2003	25-26	20	3	3	1 Lump Sum	35,000.00	35,000
Pool Pumps & Equipment Annual Allowan		22-23	1	0	0	1 Lump Sum	5,000.00	5,000
Pool Resurfacing/Tile	2015	29-30	15	0	7	1 Lump Sum	228,000.00	228,000 \$353,740
Swimming Pool - General - Total								\$353,740
Pool House								
Asphalt Shingles	2003	22-23	20	0	0	18 Squares	440.00	7,920
Exterior Painting	2012	22-23	10	0	0	3,500 Square Feet	2.00	7,000
Refurbishment Allowance - Restrooms	2003	22-23	20	0	0	1 Lump Sum	6,200.00	6,200
Standing Seam Metal Roof	2003	37-38	35	0	15	100 Square Feet	16.00	1,600
Pool House - Total						•		\$22,720
Pool Shade Structures								
	2022	21 22	10	0	0	1 I C	4 000 00	4.000
Exterior Painting - Pavilion	2022	31-32	10	0	9	1 Lump Sum	4,000.00	4,000
Standing Seam Metal Roof - Pavilion	2003 2003	37-38 27-28	35 20	0 5	15 5	1,662 Square Feet	16.00	26,592
Wood Pergola Replacement Pool Shade Structures - Total	2003	21-28	20	3	3	1,280 Square Feet	28.00	35,840 \$66,432
rooi Silade Structures - Total								\$00,432
Pool Slide & Tower								
Aluminium Railings - Pool Slide Tower	2003	27-28	25	0	5	160 Linear Feet	64.00	10,240
Pool Slide Refurbishment Allowance	2019	28-29	10	0	6	1 Lump Sum	16,000.00	16,000
Pool Slide Tower Painting	2010	23-24	10	4	1	1 Lump Sum	12,000.00	12,000
Shade Structures - Pool Side Tower	2016	30-31	15	0	8	1 Lump Sum	18,000.00	18,000
Standing Seam Metal Roof - Slide Tower	2003	37-38	35	0	15	400 Square Feet	16.00	6,400
Pool Slide & Tower - Total								\$62,640
Park - Fall Creek								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches -Back to Back	2003	22-23	16	-4	0	1 Each	2,300.00	2,300
1 min Delicited Buck to Buck	2003		10	т	9	. Lucii	2,500.00	2,300

		\$ \$ \$	de di		Qoqiani Qoqiani	e [©] o		
5	Ough Sty		ig 25			Sign ⁵	عظ والمنافعة	Chronic Const
Description	2, 0	\$6,76	2	₹ ⁰	\$0	2	\$ 6	88
Park - Fall Creek continued								
Picnic Table	2003	22-23	16	3	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	290 Linear Feet	21.00	6,090
Play Equipment Allowance	2003	22-23	15	5	0	1 Lump Sum	50,000.00	50,000
Vinyl Ranch Fence Park - Fall Creek - Total	2003	32-33	30	0	10	552 Linear Feet	24.00	13,248 \$82,238
Park - Natures Hammock								
Bi-pod Swing Set - Two Bay	2021	35-36	15	0	13	1 Each	3,200.00	3,200
Fence/Gates - Dog Park	2020	37-38	18	0	15	380 Linear Feet	26.00	9,880
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches -Back to Back	2021	36-37	16	0	14	Each	2,300.00	2,300
Picnic Table	2021	36-37	16	0	14	2 Each	1,300.00	2,600
Plastic Play Surface Border	2021	40-41	20	0	18	280 Linear Feet	21.00	5,880
Play Equipment Allowance	2021	35-36	15	0	13	1 Lump Sum	30,000.00	30,000
Scoop Digger	2021	35-36	15	0	13	1 Each	2,100.00	2,100
Vinyl Ranch Fence	2003	32-33	30	0	10	232 Linear Feet	24.00	5,568
Park - Natures Hammock - Total								\$66,328
Park - Timberfield								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	6.20	3,720
Park Benches -Back to Back	2003	22-23	16	4	0	Each	2,300.00	2,300
Picnic Table	2003	22-23	16	3	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	330 Linear Feet	21.00	6,930
Play Equipment Allowance	2003	22-23	15	5	0	1 Lump Sum	30,000.00	30,000
Vinyl Ranch Fence	2003	32-33	30	0	10	554 Linear Feet	24.00	<u>13,296</u>
Park - Timberfield - Total								\$62,046
Park - Stonebrier								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches -Back to Back	2003	23-24	16	5	1	Each	2,300.00	2,300
Picnic Table	2003	22-23	16	3	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	260 Linear Feet	21.00	5,460
Play Equipment Allowance	2003	22-23	15	5	0	1 Lump Sum	30,000.00	30,000
Scoop Digger	2003	22-23	15	3	0	1 Each	2,100.00	2,100
Spring Rider	2003	22-23	15	3	0	1 Each	1,600.00	1,600
Vinyl Ranch Fence Park - Stonebrier - Total	2003	27-28	30	-5	5	606 Linear Feet	24.00	<u>14,544</u> \$66,604
Park - Worthngton Oaks								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches -Back to Back	2003	22-23	16	3	0	1 Each	2,300.00	2,300

		,	ejt		est.	&		
	Ope St.	క _{్ర} స్ట్రా	يه وه ريون	> ```	Seguiti	Digit ^o	* *	CHECOS COS
Description	ಶ್ರ್ಯ ಲೈ	\$66,76	" 5°	₹°	, S o,	Ter	Jill Cost	03, CO.
Park - Worthngton Oaks continued								
Picnic Table	2003	22-23	16	3	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	310 Linear Feet	21.00	6,510
Play Equipment Allowance	2003	22-23	15	5	0	1 Lump Sum	30,000.00	30,000
Vinyl Ranch Fence	2003	32-33	30	0	10	410 Linear Feet	24.00	9,840
Park - Worthngton Oaks - Total								\$59,250
Park - Oakbrook								
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Bench	2003	22-23	16	0	0	1 Each	1,300.00	1,300
Picnic Table	2003	22-23	16	2	0	1 Each	1,300.00	_1,300
Park - Oakbrook - Total								\$7,400
Park - Silverleaf								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches -Back to Back	2003	23-24	16	5	1	1 Each	2,300.00	2,300
Picnic Table	2003	22-23	16	3	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	250 Linear Feet	21.00	5,250
Play Equipment Allowance	2021	35-36	15	0	13	1 Lump Sum	40,000.00	40,000
Vinyl Ranch Fence	2003	32-33	30	0	10	454 Linear Feet	24.00	10,896
Park - Silverleaf - Total								\$69,046
Park - Club House								
Bi-Pod Swing Set One Bay	2003	22-23	15	0	0	1 Each	2,200.00	2,200
Bi-Pod Swing Set Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Park Benches	2003	22-23	16	3	0	8 Each	1,300.00	10,400
Play Equipment	2003	22-23	15	5	0	1 Lump Sum	30,000.00	30,000
Scoop Digger	2003	22-23	15	3	0	1 Each	2,100.00	2,100
Spring Rider	2003	22-23	15	3	0	3 Each	1,600.00	4,800
Park - Club House - Total								\$52,700
Park - Sport Field								
Play Equipment Allowance - Playground	2003	22-23	15	5	0	1 Lump Sum	30,000.00	30,000
Scoop Digger - Playground	2003	22-23	15	3	0	1 Each	2,100.00	2,100
Spring Rider - Playground Park - Sport Field - Total	2003	22-23	15	3	0	1 Each	1,600.00	1,600 \$33,700
Park - The Oaks								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches	2003	22-23	16	1	0	1 Each	1,300.00	1,300
Picnic Table	2003	22-23	16	2	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	260 Linear Feet	21.00	5,460
Play Equipment Allowance	2003	22-23	15	3	0	1 Lump Sum	30,000.00	30,000

		a ⁴	gent		rent :	E ^{SO}		
Description	Original Control	ç	is S		Solid Solid	Sidis.	Jill OF	Care Cost
Park - The Oaks continued								
Vinyl Ranch Fence Park - The Oaks - Total	2003	32-33	30	0	10	200 Linear Feet	24.00	4,800 \$52,160
Park - Cannons Point								
Bi-pod Swing Set - Two Bay	2003	22-23	15	0	0	1 Each	3,200.00	3,200
Cresent Climber	2003	22-23	18	0	0	1 Each	2,800.00	2,800
Gazebo Roof	2003	32-33	30	0	10	600 Square Feet	8.00	4,800
Park Benches -Back to Back	2003	22-23	16	-4	0	Each	2,300.00	2,300
Picnic Table	2003	22-23	16	3	0	2 Each	1,300.00	2,600
Plastic Play Surface Border	2003	22-23	20	0	0	310 Linear Feet	21.00	6,510
Play Equipment Allowance	2003	22-23	15	5	0	1 Lump Sum	30,000.00	30,000
Scoop Digger	2003	22-23	15	3	0	1 Each	2,100.00	2,100
Spring Rider	2003	22-23	15	3	0	1 Each	1,600.00	1,600
Vinyl Ranch Fence	2003	32-33	30	0	10	365 Linear Feet	24.00	8,760
Park - Cannons Point - Total								\$64,670
Operating Expense								
Ice Machine - Club Romm	U_{i}	nfunded						
Metal Trash Cans	U_{i}	nfunded						
Wood Repair/Painting - Pool Pergola Operating Expense - Total	U	nfunded						
Components Not Included								
Cardio Room Wood Floor Replacement	U_i	nfunded						
Glass Display Refrigerator	2010	23-24	12	2	1	1 Each	2,100.00	2,100
Ice Machine	2003	22-23	15	2	0	1 Each	4,000.00	4,000
Pool Slide Replacement	U_{i}	nfunded						
Components Not Included - Total								\$6,100
Total Asset Summary								\$2,859,449

Asset II	DDescription	Replacement	Page
Site Co	omponents - General		
1173	Alumnium Flag Pole	32-33	5-15
1172	Fountain Replacement Allowance - East Pond	26-27	5-15
1170	Irrigation Pump 1	22-23	5-15
1171	Irrigation Pump 2	23-24	5-15
1169	Irrigation System Repair Allowance	22-23	5-16
Site Co	omponents - Monuments & Signage		
1193	Entry Sign Refurbishment - Cannons Point	29-30	5-17
1191	Entry Sign Refurbishment - Fall Creek	29-30	5-17
1192	Entry Sign Refurbishment - Natures Hammock	29-30	5-17
1190	Entry Sign Refurbishment - Oakleaf	29-30	5-18
1194	Entry Sign Refurbishment - Silverleaf	29-30	5-18
1189	Entry Sign Refurbishment - The Oaks	29-30	5-18
1195	Entry Sign Refurbishment - Timberfield	29-30	5-19
1198	Entry Sign Refurbishment Allowance - Amenity	22-23	5-19
1196	Refurbishment Allowance - Brick Columns	29-30	5-19
1197	Standing Seam Roof - Amenity Entry Feature	37-38	5-20
Site Co	omponents - Fencing		
1062	Vinyl Privacy Fence - Oakleaf Village Parkway	32-33	5-21
1060	Vinyl Privacy Fence - Plantation Oaks Blvd.	32-33	5-21
1059	Vinyl Ranch Fence - Oakleaf Village Parkway	32-33	5-21
1061	Vinyl Ranch Fence - Plantation Oaks Blvd. Lot	32-33	5-22
Site Co	omponents - Parking Lots		
1001	Asphalt Mil/Overlay - Amenity Lot	26-27	5-23
1002	Asphalt Mill/Overlay - P.O.B. Lot	26-27	5-23
1002	Asphalt Mill/Overlay - P.O.B. Lot (New)	40-41	5-23
1004	Concrete Paver Replacement - Amenity Lot	32-33	5-24
1005	Decorative Light Poles - Amenity Lot	27-28	5-24
1006	Dumpster Enclosure Gates	27-28	5-25
1003	Site Concrete Replacement Allowance	24-25	5-25
Site Co	omponents - Bridges & Bulkheads		
1174	Pedestrian East Bridge Painting	32-33	5-26
1174	Pedestrian Nature Walk Bridge Painting	31-32	5-26
1176	Pedestrian South West Bridge Painting	32-33	5-26

Asset I	DDescription	Replacement	Page
Site Co	omponents - Bridges & Bulkheads Continued		
1175	Pedestrian West Bridge Painting	32-33	5-27
1177	Wood Bulkhead - East Bridge	30-31	5-27
1180	Wood Bulkhead - OVP Pond	30-31	5-27
1178	Wood Bulkhead - SouthWest Bridge	30-31	5-28
1179	Wood Bulkhead - West Bridge	30-31	5-28
Site Co	omponents - Sport Field		
1184	Asphalt Replacement (4 Phases of Replacement)	28-29	5-29
1186	Decorative Light Poles	24-25	5-29
1181	Light Bollards	24-25	5-29
	Outdoor Fitness Equip. Allowance	41-42	5-30
1185	Park Benches	22-23	5-30
1183	Picnic Tables	22-23	5-30
Clubh	ouse - General		
1011	Access Control Panel	29-30	5-31
1017	Brick Tuck Point & Seal Allowance	22-23	5-31
1016	Ceiling Fans - Exterior	22-23	5-31
1008	Exterior Trim Paint	22-23	5-31
1009	Interior Painting	25-26	5-32
1010	Office Furniture Allowance	24-25	5-32
1012	Security Camera System Allowance	23-24	5-32
1015	Vinyl Ceiling/Trim	32-33	5-33
1018	Water Coolers	31-32	5-33
1014	Wood Pergola - Ext Porch	27-28	5-33
Club I	House - Roofing		
1188	Concrete Tiles/Underlayment	37-38	5-34
1187	Standing Seam Metal Roof	37-38	5-34
Clubh	ouse - Locker Rooms		
1067	Refurbishment Allowance	28-29	5-35
Clubh	ouse - Club Room & Kitchen		
1075	Electric Range	26-27	5-36
1070	Floor Tile - Club Room	30-31	5-36
1073	Floor Tile - Kitchen	30-31	5-36

Asset I	DDescription	Replacement	Page
Clubho	ouse - Club Room & Kitchen Continued		
1069	Furniture Allowance - Club Room	22-23	5-37
1076	Refrigerator	26-27	5-37
1013	Vinyl Flooring - Offices	40-41	5-37
1074	Wood Cabinet & Laminate Top - Kitchen	27-28	5-38
1071	Wood Cabinets & Stone Top - Club Room	32-33	5-38
1072	Wood Credenza & Stone Top - Club Room	32-33	5-38
Clubh	ouse - Mechanical Systems		
1078	HVAC - Clubhouse West Wing	22-23	5-39
1077	HVAC Unit - Club Room	22-23	5-39
Field I	House		
1040	Concrete Tiles/Underlayment	37-38	5-40
1043	Exterior Painting	22-23	5-40
1037	Park Bench	23-24	5-41
1038	Picnic Table	23-24	5-41
1034	Refurbishment Allowance - Restrooms	22-23	5-41
1039	Standing Seam Metal Roof	37-38	5-42
1036	Vinyl Ceiling/Trim	32-33	5-42
1035	Water Coolers	35-36	5-43
Fitness	s Center		
1056	Aluminium Fence	32-33	5-44
1057	Asphalt Shinge Roof	31-32	5-44
1054	Carpet Tiles - Strength Room	24-25	5-44
1047	Coffee Bar Cabinets & Top	27-28	5-45
1058	Exterior Painting	22-23	5-45
1053	Fitness Equipment Annual Allowance	22-23	5-45
1044	Floor Tile - Lobby	31-32	5-45
1055	HVAC System	23-24	5-46
	Interior Painting	28-29	5-46
1049	Reception Desk Cabinets	31-32	5-46
1048	Reception Desk Solid Surface Top	31-32	5-47
1051	Refurbishment Allowance - Restrooms	31-32	5-47
1045	Water Cooler - ADA Bi-Level	28-29	5-47
1046	Wood Flooring Refinishing - Cardio Room	31-32	5-48

Asset I	DDescription	Replacement	Page
Rasket	ball Courts		
1081	Basketball Poles & Goals	29-30	5-49
1080	Chain Link Fence	29-30	5-49
1079	Court Resurfacing	25-26	5-49
1082	Light Poles	29-30	5-49
TD •			
1086	Courts Chain Link Fence - 10 Ft	29-30	5-50
1084	Chain Link Fence - 10 Ft Chain Link Fence - 4 Ft	29-30	5-50 5-50
1084	Court Resurfacing	25-26	5-50
1083	Light Poles	29-30	5-50
1087	Shade Structures	24-25	5-50 5-51
1003	Shade Structures	24-23	3-31
Swimr	ning Pool - General		
1022	Aluminium Fence	32-33	5-52
1025	Lane Divider Reel	27-28	5-52
1024	Lane Dividers	22-23	5-52
1021	Lifeguard Chairs	23-24	5-52
1023	Pool Furniture Replacement Allowance	26-27	5-53
1026	Pool Lift	24-25	5-53
1027	Pool Play Equipment Allowance	25-26	5-53
1020	Pool Pumps & Equipment Annual Allowance	22-23	5-54
1019	Pool Resurfacing/Tile	29-30	5-54
Pool H	louse		
1032	Asphalt Shingles	22-23	5-55
1029	Exterior Painting	22-23	5-55
1031	Refurbishment Allowance - Restrooms	22-23	5-55
1028	Standing Seam Metal Roof	37-38	5-55
Dool C	hada Churchana		
	hade Structures	21 22	5 56
1161	Exterior Painting - Pavilion	31-32	5-56
1160	Standing Seam Metal Roof - Pavilion	37-38	5-56
1162	Wood Pergola Replacement	27-28	5-56
Pool S	lide & Tower		
1166	Aluminium Railings - Pool Slide Tower	27-28	5-57
1167	Pool Slide Refurbishment Allowance	28-29	5-57

Asset I	DDescription	Replacement	Page
Pool Si	lide & Tower Continued		
1168	Pool Slide Tower Painting	23-24	5-57
1164	Shade Structures - Pool Side Tower	30-31	5-58
1165	Standing Seam Metal Roof - Slide Tower	37-38	5-58
Park -	Fall Creek		
1110	Bi-pod Swing Set - Two Bay	22-23	5-59
1107	Gazebo Roof	32-33	5-59
1108	Park Benches -Back to Back	22-23	5-60
1111	Picnic Table	22-23	5-60
1109	Plastic Play Surface Border	22-23	5-61
1105	Play Equipment Allowance	22-23	5-61
1106	Vinyl Ranch Fence	32-33	5-62
Park -	Natures Hammock		
1118	Bi-pod Swing Set - Two Bay	35-36	5-63
1118	Fence/Gates - Dog Park	37-38	5-63
1115	Gazebo Roof	32-33	5-63
1119	Park Benches -Back to Back	36-37	5-64
1120	Picnic Table	36-37	5-64
1112	Plastic Play Surface Border	40-41	5-65
1114	Play Equipment Allowance	35-36	5-65
1117	Scoop Digger	35-36	5-66
1113	Vinyl Ranch Fence	32-33	5-66
Park -	Timberfield		
1122	Bi-pod Swing Set - Two Bay	22-23	5-68
1121	Gazebo Roof	32-33	5-68
1123	Park Benches -Back to Back	22-23	5-68
1125	Picnic Table	22-23	5-68
1127	Plastic Play Surface Border	22-23	5-69
1126	Play Equipment Allowance	22-23	5-69
1124	Vinyl Ranch Fence	32-33	5-69
Park -	Stonebrier		
1128	Bi-pod Swing Set - Two Bay	22-23	5-70
1131	Gazebo Roof	32-33	5-70
1133	Park Benches -Back to Back	23-24	5-70

Asset I	DDescription	Replacement	Page
Park -	Stonebrier Continued		
1136	Picnic Table	22-23	5-70
1135	Plastic Play Surface Border	22-23	5-71
1129	Play Equipment Allowance	22-23	5-71
1132	Scoop Digger	22-23	5-71
1130	Spring Rider	22-23	5-71
1134	Vinyl Ranch Fence	27-28	5-72
Park -	Worthngton Oaks		
1138	Bi-pod Swing Set - Two Bay	22-23	5-73
1140	Gazebo Roof	32-33	5-73
1143	Park Benches -Back to Back	22-23	5-73
1142	Picnic Table	22-23	5-73
1137	Plastic Play Surface Border	22-23	5-74
1139	Play Equipment Allowance	22-23	5-74
1141	Vinyl Ranch Fence	32-33	5-74
Park -	Oakbrook		
1089	Gazebo Roof	32-33	5-75
1090	Park Bench	22-23	5-75
1088	Picnic Table	22-23	5-76
Park -	Silverleaf		
1094	Bi-pod Swing Set - Two Bay	22-23	5-77
1093	Gazebo Roof	32-33	5-77
1095	Park Benches -Back to Back	23-24	5-78
1097	Picnic Table	22-23	5-78
1092	Plastic Play Surface Border	22-23	5-79
1091	Play Equipment Allowance	35-36	5-79
1096	Vinyl Ranch Fence	32-33	5-80
Park -	Club House		
1159	Bi-Pod Swing Set One Bay	22-23	5-81
1154	Bi-Pod Swing Set Two Bay	22-23	5-81
1155	Park Benches	22-23	5-81
1157	Play Equipment	22-23	5-81
1158	Scoop Digger	22-23	5-82
1156	Spring Rider	22-23	5-82

Asset I	DDescription	Replacement	Page
Park -	Sport Field		
1199	Play Equipment Allowance - Playground	22-23	5-83
1201	Scoop Digger - Playground	22-23	5-83
1200	Spring Rider - Playground	22-23	5-84
Dork -	The Oaks		
1099	Bi-pod Swing Set - Two Bay	22-23	5-85
1102	Gazebo Roof	32-33	5-85
1102	Park Benches	22-23	5-85
1103	Picnic Table	22-23	5-85
1103	Plastic Play Surface Border	22-23	5-86
1098	Play Equipment Allowance	22-23	5-86
1101	Vinyl Ranch Fence	32-33	5-86
1101	Vinyi Kanch Pence	32-33	3-60
Park -	Cannons Point		
1145	Bi-pod Swing Set - Two Bay	22-23	5-87
1151	Cresent Climber	22-23	5-87
1148	Gazebo Roof	32-33	5-87
1149	Park Benches -Back to Back	22-23	5-87
1153	Picnic Table	22-23	5-88
1152	Plastic Play Surface Border	22-23	5-88
1146	Play Equipment Allowance	22-23	5-88
1150	Scoop Digger	22-23	5-89
1144	Spring Rider	22-23	5-89
1147	Vinyl Ranch Fence	32-33	5-89
Onera	ting Expense		
1076	Ice Machine - Club Romm	22-23	5-90
1070	Metal Trash Cans	22-23	5-90
1163	Wood Repair/Painting - Pool Pergola	22-23	5-90
1103	wood repair anding 1 ooi reigon	22 23	3 70
Compo	onents Not Included		
	Cardio Room Wood Floor Replacement	22-23	5-91
1042	Glass Display Refrigerator	23-24	5-91
1041	Ice Machine	22-23	5-91
1167	Pool Slide Replacement	22-23	5-91
	Total Funded Assets	193	
	Total Unfunded Assets	5	
	Total Assets	198	

Alumnium Flag Pole - 20	032	1 Each	@ \$3,500.00
Asset ID	1173	Asset Actual Cost	\$3,500.00
		Percent Replacement	100%
Site Com	ponents - General	Future Cost	\$4,982.61
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		
Fountain Replacement A	llowance - East Por	nd - 2026	
		1 Each	@ \$5,000.00
Asset ID	1172	Asset Actual Cost	\$5,000.00
		Percent Replacement	100%
Site Com	ponents - General	Future Cost	\$5,961.23
Placed in Service	June 2019		
Useful Life	8		
Replacement Year	26-27		
Remaining Life	4		
Irrigation Pump 1 - 2022		15 HP	@ \$420.00
Asset ID	1170	Asset Actual Cost	\$6,300.00
		Percent Replacement	100%
Site Com	ponents - General	Future Cost	\$6,300.00
Placed in Service	June 2003		
Useful Life	12		
Replacement Year	22-23		
Remaining Life	0		
Irrigation Pump 2 - 2023		15 110	Θ Φ4 2 0.00
Asset ID		15 HP	@ \$420.00
Asset ID	1171	Asset Actual Cost	\$6,300.00
Sita Cam	nonanta Canaval	Percent Replacement Future Cost	100% \$6,678.00
Placed in Service	ponents - General June 2003	ruture Cost	φυ,0/8.UU
Useful Life	June 2003 12		
Adjustment	9		
•			
-			
Replacement Year Remaining Life	23-24 1		

Irrigation System Repair Allowance - 2022

Asset ID	1169	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$3,000.00 \$3,000.00 100%
Site	Components - General	Future Cost	\$3,000.00
Placed in Service	June 2015		
Useful Life	5		
Replacement Year	22-23		
Remaining Life	0		

Entry Sign Refurbishment - Cannons Point - 2029

																	I	L	ιu	n	η)	5	u	n	1		(\underline{a}		Þ.:	5,	8	U	J.	U	U
Asset ID	1193												A	S	S	et	1	١	ct	u	a	1	C	o	S	t				(\$3	3,	8	0	Э.	0	0
										P	e	er	c	e	n	t :	R	e	p.	a	c	e	m	e	n	t								1()()%	6
Site Components - N	Monuments & Signage]	٦	ıt	u	re	•	C	O	S	t				(\$4	1,	9	5(Э.	6	4
Placed in Service	June 2020																																				
Useful Life	10																																				
Replacement Year	29-30																																				
Remaining Life	7																																				

Entry Sign Refurbishment - Fall Creek - 2029

		1 Lump Sum	@ \$3,800.00
Asset ID	1191	Asset Actual Cost	\$3,800.00
		Percent Replacement	100%
Site Components - 3	Monuments & Signage	Future Cost	\$4,950.64
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Entry Sign Refurbishment - Natures Hammock - 2029

		1 Lump Sum	@ \$3,800.00
Asset ID	1192	Asset Actual Cost	\$3,800.00
		Percent Replacement	100%
Site Components - Monu	ments & Signage	Future Cost	\$4,950.64
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Entry Sign Refurbishment - Oakleaf - 2029

Asset ID	1190	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$15,700.00 \$15,700.00 100%
Site Components - M	Ionuments & Signage	Future Cost	\$20,453.94
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Entry Sign Refurbishment - Silverleaf - 2029

		1 Lump Sum	@ \$3,800.00
Asset ID	1194	Asset Actual Cost	\$3,800.00
		Percent Replacement	100%
Site Components - N	Monuments & Signage	Future Cost	\$4,950.64
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Entry Sign Refurbishment - The Oaks - 2029

		1 Each	@ \$3,800.00
Asset ID	1189	Asset Actual Cost	\$3,800.00
		Percent Replacement	100%
Site Components - M	Ionuments & Signage	Future Cost	\$4,950.64
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Entry Sign Refurbishment - Timberfield - 2029

Asset ID	1195	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$3,800.00 \$3,800.00 100%
Site Components - N	Monuments & Signage	Future Cost	\$4,950.64
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		

Entry Sign Refurbishment Allowance - Amenity - 2022

		I Lump Sum	@ \$12,000.00
Asset ID	1198	Asset Actual Cost	\$12,000.00
		Percent Replacement	100%
Site Components - I	Monuments & Signage	Future Cost	\$12,000.00
Placed in Service	June 2003		
Useful Life	10		
Replacement Year	22-23		
Remaining Life	0		

Includes brick cleaning and tuck point, painting of other sections.

Refurbishment Allowance - Brick Columns - 2029

		1 Lump Sum	@ \$5,400.00
Asset ID	1196	Asset Actual Cost	\$5,400.00
		Percent Replacement	100%
Site Components - N	Monuments & Signage	Future Cost	\$7,035.11
Placed in Service	June 2020		
Useful Life	10		
Replacement Year	29-30		
Remaining Life	7		
Replacement Year			

Standing Seam Roof - Amenity Entry Feature - 2037

			140 Square Feet	@ \$19.00
	Asset ID	1197	Asset Actual Cost	\$2,660.00
			Percent Replacement	100%
Site Cor	nponents - Mo	onuments & Signage	Future Cost	\$4,389.92
Placed	in Service	June 2003		
Į	Jseful Life	35		
Replace	ment Year	37-38		
Rem	aining Life	15		

Vinyl Privacy Fence - Oakleaf Village Parkway - 2032

			6,831 Linear Feet	@ \$36.00
Asset	ID	1062	Asset Actual Cost	\$245,916.00
			Percent Replacement	100%
Site Components - Fencing		s - Fencing	Future Cost	\$350,086.90
Placed in Serv	vice	June 2003		
Useful I	Life	30		
Replacement Y	ear	32-33		
Remaining I	Life	10		

Vinyl Privacy Fence - Plantation Oaks Blvd. - 2032

Asset ID	1060	2,592 Linear Feet Asset Actual Cost Percent Replacement	@ \$36.00 \$93,312.00 100%
Site Components - Fencing		Future Cost	\$132,839.30
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

Vinyl Ranch Fence - Oakleaf Village Parkway - 2032

		1,594 Linear Feet	@ \$24.00
Asset ID	1059	Asset Actual Cost	\$38,256.00
		Percent Replacement	100%
Site Components - Fencing		Future Cost	\$54,461.38
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

Vinyl Ranch Fence - Plantation Oaks Blvd. Lot - 2032

		846 Linear Feet	@ \$24.00
Asset ID	1061	Asset Actual Cost	\$20,304.00
		Percent Replacement	100%
Site Components - Fencing		Future Cost	\$28,904.85
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

Asphalt Mil/Overlay - Amenity Lot - 2026

Asset ID	1001	5,800 Square Yards Asset Actual Cost Percent Replacement	@ \$17.10 \$99,180.00 100%
Site Compo	nents - Parking Lots	Future Cost	\$118,246.92
Placed in Service	June 2003		
Useful Life	20		
Adjustment	4		
Replacement Year	26-27		
Remaining Life	4		

Asphalt Mill/Overlay - P.O.B. Lot - 2026

		4,200 Square Yards	@ \$17.10
Asset ID	1002	Asset Actual Cost	\$71,820.00
		Percent Replacement	100%
Site Comp	ponents - Parking Lots	Future Cost	\$85,627.08
Placed in Service	June 2003		
Useful Life	20		
Adjustment	4		
Replacement Year	26-27		
Remaining Life	4		

Asphalt Mill/Overlay - P.O.B. Lot (New) - 2040

		2,100 Square Yards	@ \$17.10
Asset ID	1002	Asset Actual Cost	\$35,910.00
		Percent Replacement	100%
Site Components - Parking Lots		Future Cost	\$64,759.32
Placed in Service	June 2021		
Useful Life	20		
Replacement Year	40-41		
Remaining Life	18		

Asphalt Mill/Overlay - P.O.B. Lot (New) continued...



Concrete Paver Replacement - Amenity Lot - 2032

	10,700 Square Feet	@ \$8.15
1004	Asset Actual Cost	\$87,205.00
	Percent Replacement	100%
Site Components - Parking Lots		\$124,145.35
June 2003		
30		
32-33		
10		
•	nents - Parking Lots June 2003 30 32-33	Percent Replacement Future Cost June 2003 30 32-33

Decorative Light Poles - Amenity Lot - 2027

Asset ID	1005	8 Each Asset Actual Cost Percent Replacement	@ \$1,800.00 \$14,400.00 100%
Site Components - Parking Lots		Future Cost	\$17,683.39
Placed in Service	June 2003		
Useful Life	25		
Replacement Year	27-28		
Remaining Life	5		

Dumpster Enclosure Gates	- 2027	2 Each	@ \$2,000.00
Asset ID	1006	Asset Actual Cost	\$4,000.00
		Percent Replacement	100%
Site Components	- Parking Lots	Future Cost	\$4,912.05
Placed in Service	June 2003		
Useful Life	20		
Adjustment	5		
Replacement Year	27-28		
Remaining Life	5		

Site Concrete Replacement Allowance - 2024

Asset ID	1003	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$10,000.00 \$10,000.00 100%
Site Compo	nents - Parking Lots	Future Cost	\$11,130.00
Placed in Service	June 2015		
Useful Life	10		
Replacement Year	24-25		
Remaining Life	2		

Pedestrian East Bridge Painting - 2032

Asset ID	1174	1 Lump Sum Asset Actual Cost	@ \$4,000.00 \$4,000.00
		Percent Replacement	100%
Site Components -	Bridges & Bulkheads	Future Cost	\$5,694.41
Placed in Service	June 2021		
Useful Life	12		
Replacement Year	32-33		
Remaining Life	10		

Pedestrian Nature Walk Bridge Painting - 2031

		1 Lump Sum	@ \$4,000.00
Asset ID	1174	Asset Actual Cost	\$4,000.00
		Percent Replacement	100%
Site Components -	Bridges & Bulkheads	Future Cost	\$5,528.56
Placed in Service	June 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	9		



Pedestrian South West Bridge Painting - 2032

Asset ID	1176	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$4,000.00 \$4,000.00 100%
Site Components -	Bridges & Bulkheads	Future Cost	\$5,694.41
Placed in Service	June 2021		
Useful Life	12		
Replacement Year	32-33		
Remaining Life	10		

Pedestrian West Brid	lge Painting - 2032		
Asset ID	1175	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$4,000.00 \$4,000.00 100%
Site Components -	Bridges & Bulkheads	Future Cost	\$5,694.41
Placed in Service	June 2021		+-,
Useful Life	12		
Replacement Year	32-33		
Remaining Life	10		
Wood Bulkhead - Ea	st Bridge - 2030		
		132 Linear Feet	@ \$124.00
Asset ID	1177	Asset Actual Cost	\$16,368.00
		Percent Replacement	100%
*	Bridges & Bulkheads	Future Cost	\$21,963.94
Placed in Service	June 2003		
Useful Life	28		
Replacement Year	30-31		
Remaining Life	8		
Wood Bulkhead - O'	VP Pond - 2030		
		240 Linear Feet	@ \$124.00
Asset ID	1180	Asset Actual Cost	\$29,760.00
		Percent Replacement	100%
	Bridges & Bulkheads	Future Cost	\$39,934.44
Placed in Service	June 2003		
Useful Life	28		
Replacement Year	30-31		
Remaining Life	8		

Wood Bulkhead - South'	West Bridge	- 2030
------------------------	-------------	--------

Asset ID	1178	140 Linear Feet Asset Actual Cost Percent Replacement	@ \$124.00 \$17,360.00 100%
Site Components -	Bridges & Bulkheads	Future Cost	\$23,295.09
Placed in Service	June 2003		
Useful Life	28		
Replacement Year	30-31		
Remaining Life	8		

Wood Bulkhead - West Bridge - 2030

		148 Linear Feet	@ \$124.00
Asset ID	1179	Asset Actual Cost	\$18,352.00
		Percent Replacement	100%
Site Components -	Bridges & Bulkheads	Future Cost	\$24,626.24
Placed in Service	June 2003		
Useful Life	28		
Replacement Year	30-31		
Remaining Life	8		

Asphalt Replacement (4 Phases of Replacement) - 2028

		448 Square Yards	@ \$24.00
Asset ID	1184	Asset Actual Cost	\$10,752.00
		Percent Replacement	100%
Site Compone	ents - Sport Field	Future Cost	\$13,599.70
Placed in Service	June 2021		
Useful Life	8		
Replacement Year	28-29		
Remaining Life	6		



Total of approx 1,791 SY of which about 25% was replaced in 2021. Included is a phased replacement of 448 Sy every 8 years.

Decorative Light Poles - 2	2024	19 Each	@ \$1,800.00
Asset ID	1186	Asset Actual Cost	\$34,200.00
		Percent Replacement	100%
Site Compone	nts - Sport Field	Future Cost	\$38,064.60
Placed in Service	June 2003		
Useful Life	22		
Replacement Year	24-25		
Remaining Life	2		
_			

Light Bollards - 2024		10 Each	@ \$600.00
Asset ID	1181	Asset Actual Cost	\$6,000.00
		Percent Replacement	100%
Site Compone	nts - Sport Field	Future Cost	\$6,678.00
Placed in Service	June 2003		
Useful Life	22		
Replacement Year	24-25		
Remaining Life	2		

Community Advisors Page 5-29 May 9, 2022

Outdoor Fitness Equip. Allowance - 2041

	12 Units	@ \$2,200.00
Asset ID	Asset Actual Cost	\$26,400.00
	Percent Replacement	100%
Site Components - Sport Field	Future Cost	\$49,037,47

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
June 2017
41-42

Remaining Life



Park Benches - 2022 @ \$1,300.00 8 Each Asset ID 1185 Asset Actual Cost \$10,400.00 Percent Replacement 100% Site Components - Sport Field **Future Cost** \$10,400.00 Placed in Service June 2003 Useful Life 16 Adjustment 3 Replacement Year 22-23 Remaining Life 0

Picnic Tables - 2022		5 Each	@ \$1,800.00
Asset ID	1183	Asset Actual Cost	\$9,000.00
		Percent Replacement	100%
Site Component	ts - Sport Field	Future Cost	\$9,000.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	3		
Replacement Year	22-23		

0

Access Control Pane	el - 2029	1 Lump Sum	@ \$3,800.00
Asset ID	1011	Asset Actual Cost Percent Replacement	\$3,800.00 100%
	Clubhouse - General	Future Cost	\$4,950.64
Placed in Service	June 2015		+ 1,5 2 3 1 2 1
Useful Life	15		
Replacement Year	29-30		
Remaining Life	7		
Brick Tuck Point &	Seal Allowance - 2022		
		2,500 Stalls	@ \$6.20
Asset ID	1017	Asset Actual Cost	\$15,500.00
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$15,500.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		
Ceiling Fans - Exteri	or - 2022	14 Each	@ \$400.00
Ceiling Fans - Exteri	or - 2022	14 Each Asset Actual Cost	\$5,600.00
Asset ID		Asset Actual Cost	\$5,600.00
	1016	Asset Actual Cost Percent Replacement	\$5,600.00 100%
Asset ID	1016 Clubhouse - General June 2003 16	Asset Actual Cost Percent Replacement	\$5,600.00 100%
Asset ID Placed in Service	1016 Clubhouse - General June 2003	Asset Actual Cost Percent Replacement	\$5,600.00 100%
Asset ID Placed in Service Useful Life	1016 Clubhouse - General June 2003 16	Asset Actual Cost Percent Replacement	\$5,600.00 100%
Asset ID Placed in Service Useful Life Replacement Year Remaining Life	1016 Clubhouse - General June 2003 16 22-23 0	Asset Actual Cost Percent Replacement	\$5,600.00 100% \$5,600.00
Asset ID Placed in Service Useful Life Replacement Year Remaining Life Exterior Trim Paint -	1016 Clubhouse - General June 2003 16 22-23 0	Asset Actual Cost Percent Replacement Future Cost	\$5,600.00 100% \$5,600.00 @ \$16,400.00
Asset ID Placed in Service Useful Life Replacement Year Remaining Life	1016 Clubhouse - General June 2003 16 22-23 0	Asset Actual Cost Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost	\$5,600.00 100% \$5,600.00 @ \$16,400.00 \$16,400.00
Asset ID Placed in Service Useful Life Replacement Year Remaining Life Exterior Trim Paint -	1016 Clubhouse - General June 2003 16 22-23 0	Asset Actual Cost Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	\$5,600.00 100% \$5,600.00 \$16,400.00 \$16,400.00 100%
Asset ID Placed in Service Useful Life Replacement Year Remaining Life Exterior Trim Paint - Asset ID	1016 Clubhouse - General June 2003 16 22-23 0 2022 1008 Clubhouse - General	Asset Actual Cost Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost	\$5,600.00 100% \$5,600.00 @ \$16,400.00 \$16,400.00
Asset ID Placed in Service Useful Life Replacement Year Remaining Life Exterior Trim Paint - Asset ID Placed in Service	1016 Clubhouse - General June 2003 16 22-23 0 2022 1008 Clubhouse - General June 2003	Asset Actual Cost Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	\$5,600.00 100% \$5,600.00 \$16,400.00 \$16,400.00 100%
Asset ID Placed in Service Useful Life Replacement Year Remaining Life Exterior Trim Paint - Asset ID Placed in Service Useful Life	1016 Clubhouse - General June 2003 16 22-23 0 1008 Clubhouse - General June 2003 12	Asset Actual Cost Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	\$5,600.00 100% \$5,600.00 \$16,400.00 \$16,400.00 100%
Asset ID Placed in Service Useful Life Replacement Year Remaining Life Exterior Trim Paint - Asset ID Placed in Service	1016 Clubhouse - General June 2003 16 22-23 0 2022 1008 Clubhouse - General June 2003	Asset Actual Cost Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	\$5,600.00 100% \$5,600.00 \$16,400.00 \$16,400.00 100%

	1 Lump Sum		Interior Painting - 202
st \$4	Asset Actual Cost	1009	Asset ID
nt	Percent Replacement		
st \$5	Future Cost	lubhouse - General	
		June 2015	Placed in Service
		8	Useful Life
		3	Adjustment
		25-26	Replacement Year
		3	Remaining Life
m @ \$1	1 Lump Sum	nce - 2024	Office Furniture Allo
	Asset Actual Cost	1010	Asset ID
·	Percent Replacement	1010	115500
	Future Cost	lubhouse - General	
,		June 2003	Placed in Service
		20	Useful Life
		2	Adjustment
		24-25	Replacement Year
		2	Remaining Life
		n Allowance - 2023	Security Camera Syst
m @ \$10	1 Lump Sum		
st \$10	Asset Actual Cost	1012	Asset ID
nt	Percent Replacement		
	Future Cost	lubhouse - General	
		June 2010	Placed in Service
		10	Useful Life
		4	Adjustment
		23-24	Replacement Year
		1	D I.C

1

Remaining Life

Vinyl Ceiling/Trim -	2032	1,600 Square Feet	@ \$6.90
Asset ID	1015	Asset Actual Cost	\$11,040.00
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$15,716.58
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

Water Coolers - 2031		2 Each	@ \$2,100.00
Asset ID	1018	Asset Actual Cost	\$4,200.00
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$5,804.99
Placed in Service	June 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	9		

Wood Pergola - Ext P	Porch - 2027	400 Square Feet	@ \$28.00
Asset ID	1014	Asset Actual Cost	\$11,200.00
		Percent Replacement	100%
	Clubhouse - General	Future Cost	\$13,753.75
Placed in Service	June 2003		
TT 0 1 T 10	20		

Useful Life 20
Adjustment 5
Replacement Year 27-28
Remaining Life 5



Concrete Tiles/Underlayment - 2037

9,485 Square Feet @ \$12.00
Asset ID 1188 Asset Actual Cost \$113,820.00
Percent Replacement 100%
Club House - Roofing Future Cost \$187,842.47

Placed in Service
Useful Life
S5
Replacement Year
Remaining Life
June 2003
37-38
15



Standing Seam Metal Roof - 2037

Asset ID 1187 Asset Actual Cost \$9,600.00

600 Square Feet

@ \$16.00

Percent Replacement 100%
Club House - Roofing Future Cost \$15,843.33

Placed in Service
Useful Life
35
Replacement Year
Remaining Life
June 2003
37-38
15



Refurbishment Allowance - 2028

 ent Allowance - 2028
 2,400 Square Feet
 @ \$48.00

 Asset ID
 1067
 Asset Actual Cost Percent Replacement
 \$115,200.00

 Percent Replacement
 100%

 Clubhouse - Locker Rooms
 Future Cost
 \$145,711.11

Placed in Service June 2003
Useful Life 20
Adjustment 6
Replacement Year 28-29
Remaining Life 6



Electric Range - 2026		1 Each	@ \$1,600.00
Asset ID	1075	Asset Actual Cost	\$1,600.00
		Percent Replacement	100%
Clubhouse - Clu	b Room & Kitchen	Future Cost	\$1,907.59
Placed in Service	June 2003		
Useful Life	12		
Adjustment	12		
Replacement Year	26-27		
Remaining Life	4		

Floor Tile - Club Room - 2030

 Club Room - 2030
 1,961 Square Feet
 @ \$14.00

 Asset ID
 1070
 Asset Actual Cost
 \$27,454.00

 Percent Replacement
 100%

 ubhouse - Club Room & Kitchen
 Future Cost
 \$36,840.05

Clubhouse - Club Room & Kitchen
Placed in Service June 2003
Useful Life 20
Adjustment 8
Replacement Year 30-31
Remaining Life 8



Floor Tile - Kitchen - 2030

Asset ID 1073 Asset Actual Cost \$1,071.00
Percent Replacement 100%
Clubhouse - Club Room & Kitchen Future Cost \$1,437.16

Placed in Service
Useful Life
Adjustment
Replacement Year
Remaining Life
Useful Life
30-31
Remaining Life
8

Community Advisors Page 5-36 May 9, 2022

Furniture Allowance - Club Room - 2022

Asset ID	1069	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$3,000.00 \$3,000.00 100%
Clubhouse - Club Room & Kitchen		Future Cost	\$3,000.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		



Refrigerator - 2026			0 44 400 00
Reffigerator - 2020		1 Each	@ \$1,200.00
Asset ID	1076	Asset Actual Cost	\$1,200.00
		Percent Replacement	100%
Clubhouse - C	Club Room & Kitchen	Future Cost	\$1,430.69
Placed in Service	June 2003		
Useful Life	12		
Adjustment	12		
Replacement Year	26-27		
Remaining Life	4		

Vinyl Flooring - Offices -	2040	300 Square Feet	@ \$7.00
Asset ID	1013	Asset Actual Cost	\$2,100.00
		Percent Replacement	100%
Clubhouse - Club I	Room & Kitchen	Future Cost	\$3,787.09
Placed in Service	June 2021		
Useful Life	20		
Replacement Year	40-41		
Remaining Life	18		

Wood Cabinet & Laminate Top - Kitchen - 2027

		38 Linear Feet	@ \$185.00
Asset ID	1074	Asset Actual Cost	\$7,030.00
		Percent Replacement	100%
Clubhouse - Cl	lub Room & Kitchen	Future Cost	\$8,632.93
Placed in Service	June 2003		
Useful Life	20		
Adjustment	5		
Replacement Year	27-28		
Remaining Life	5		

Wood Cabinets & Stone Top - Club Room - 2032

		20 Linear Feet	@ \$300.00
Asset ID	1071	Asset Actual Cost	\$6,000.00
		Percent Replacement	100%
Clubhouse - Club l	Room & Kitchen	Future Cost	\$8,541.62
Placed in Service	June 2003		
Useful Life	25		
Adjustment	5		
Replacement Year	32-33		
Remaining Life	10		

Wood Credenza & Stone Top - Club Room - 2032

		12 Linear Feet	@ \$240.00
Asset ID	1072	Asset Actual Cost	\$2,880.00
		Percent Replacement	100%
Clubhouse -	Club Room & Kitchen	Future Cost	\$4,099.98
Placed in Service	June 2003		
Useful Life	25		
Adjustment	5		
Replacement Year	32-33		
Remaining Life	10		

IIVAC Clubbouse Wes	** Wina 2022		
HVAC - Clubhouse Wes	st wing - 2022	12 Tons	@ \$1,800.00
Asset ID	1078	Asset Actual Cost	\$21,600.00
		Percent Replacement	100%
Clubhouse - M	Iechanical Systems	Future Cost	\$21,600.00
Placed in Service	June 2003		
Useful Life	12		
Replacement Year	22-23		
Remaining Life	0		

Assuming system will be replaced with standard unit since fitness component has been removed.

HVAC Unit - Club Roon	n - 2022	5 Tons	@ \$1,800.00
Asset ID	1077	Asset Actual Cost	\$9,000.00
		Percent Replacement	100%
Clubhouse - Mechanical Systems		Future Cost	\$9,000.00
Placed in Service	June 2003		
Useful Life	12		
Replacement Year	22-23		
Remaining Life	0		

Concrete Tiles/Underlayment - 2037

Asset ID	1040	1,184 Square Feet Asset Actual Cost Percent Replacement	@ \$12.00 \$14,208.00 100%
	Field House	Future Cost	\$23,448.13
Placed in Service	June 2003		
Useful Life	35		
Replacement Year	37-38		
Remaining Life	15		



Ext

Remaining Life

xterior Painting - 2022		2,200 Square Feet	@ \$2.00
Asset ID	1043	Asset Actual Cost	\$4,400.00
		Percent Replacement	100%
	Field House	Future Cost	\$4,400.00
Placed in Service	June 2003		
Useful Life	10		
Adjustment	7		
Replacement Year	22-23		



0

Park Bench - 2023		4 Each	@ \$1,300.00
Asset ID	1037	Asset Actual Cost	\$5,200.00
		Percent Replacement	100%
	Field House	Future Cost	\$5,512.00
Placed in Service	June 2003		
Useful Life	15		
Adjustment	6		
Replacement Year	23-24		
Remaining Life	1		
Picnic Table - 2023		2 Each	@ \$1,300.00
Asset ID	1038	Asset Actual Cost	\$2,600.00
		Percent Replacement	100%
	Field House	Future Cost	\$2,756.00
Placed in Service	June 2003		
Useful Life	15		
Adjustment	6		
Replacement Year	23-24		
Remaining Life	1		
Refurbishment Allow	vance - Restrooms - 2022		
		1 Lump Sum	@ \$18,000.00
Asset ID	1034	Asset Actual Cost	\$18,000.00
11000011	100.	Percent Replacement	100%
	Field House	Future Cost	\$18,000.00
Placed in Service	June 2003	1 0.0020 0000	410,000.00
Useful Life	20		

-3

0

22-23

Adjustment

Replacement Year

Remaining Life

Refurbishment Allowance - Restrooms continued...



Standing Seam Metal Roof - 2037

Asset ID 1039 Ass

Placed in Service June 2003
Useful Life 35
Replacement Year 37-38
Remaining Life 15

 1,200 Square Feet
 @ \$16.00

 Asset Actual Cost
 \$19,200.00

 Percent Replacement
 100%

 Future Cost
 \$31,686.66



Vinyl Ceiling/Trim - 2032

1,200 Square Feet @ \$6.90
Asset ID 1036 Asset Actual Cost \$8,280.00
Percent Replacement 100%
Field House Future Cost \$11,787.44

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
31
32-33

Community Advisors Page 5-42 May 9, 2022

Water Coolers - 2035		2 Each	@ \$2,100.00
Asset ID	1035	Asset Actual Cost	\$4,200.00
		Percent Replacement	100%
	Field House	Future Cost	\$6,533.56
Placed in Service	June 2021		
Useful Life	15		
Replacement Year	35-36		
Remaining Life	13		

Aluminium Fence - 2032		240 Linear Feet	@ \$36.00
Asset ID	1056	Asset Actual Cost	\$8,640.00
		Percent Replacement	100%
	Fitness Center	Future Cost	\$12,299.93
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

Asphalt Shinge Roof - 2031

Remaining Life

sphalt Shinge Roof -	- 2031	44 Squares	@ \$440.00
Asset ID	1057	Asset Actual Cost	\$19,360.00
		Percent Replacement	100%
	Fitness Center	Future Cost	\$26,758.22
Placed in Service	June 2012		
Useful Life	20		
Replacement Year	31-32		

9

Carpet Tiles - Strength Room - 2024

Asset ID	1054	180 Square Yards Asset Actual Cost Percent Replacement	@ \$38.00 \$6,840.00 100%
	Fitness Center	Future Cost	\$7,612.92
Placed in Service	June 2012		
Useful Life	10		
Adjustment	3		
Replacement Year	24-25		
Remaining Life	2		



Coffee Bar Cabinets & To	op - 2027	1 Lump Sum	@ \$2,000.00
Asset ID	1047	Asset Actual Cost	\$2,000.00
		Percent Replacement	100%
	Fitness Center	Future Cost	\$2,456.03
Placed in Service	June 2012		
Useful Life	16		
Replacement Year	27-28		
Remaining Life	5		
Exterior Painting - 2022		3,600 Square Feet	@ \$2.00
Asset ID	1058	Asset Actual Cost	\$7,200.00
Asset ID	1030	Percent Replacement	100%
	Fitness Center	Future Cost	\$7,200.00
Placed in Service	June 2012	1 0.0020 0000	ψ <i>τ</i> , = 00.00
Useful Life	10		
Replacement Year	22-23		
Remaining Life	0		
Fitness Equipment Annua Asset ID Placed in Service Useful Life	1053 Fitness Center June 2015 1	1 Lump Sum Asset Actual Cost Percent Replacement Future Cost	@ \$3,000.00 \$3,000.00 100% \$3,000.00
Replacement Year	22-23		
Remaining Life	0		
Floor Tile - Lobby - 2031		800 Square Feet	@ \$16.00
Asset ID	1044	Asset Actual Cost Percent Replacement	\$12,800.00 100%
·	Fitness Center	Future Cost	\$17,691.38
Placed in Service	June 2012		
Useful Life	20		
Replacement Year	31-32		
Remaining Life	9		

HVAC System - 2023

Asset ID 1055 Asset Actual Cost \$18,000.00
Percent Replacement 100%
Fitness Center Future Cost \$19,080.00

Placed in Service
Useful Life
Replacement Year
Remaining Life
June 2012
23-24
Remaining Life
1

Interior Painting - 2028

Asset ID

Asset Actual Cost
Percent Replacement
Fitness Center

Puture Cost

\$5,000.00

\$5,000.00

\$6,324.27

Placed in Service June 2021
Useful Life 8
Replacement Year 28-29
Remaining Life 6



Reception Desk Cabinets - 2031

Asset ID 1049 Asset Actual Cost \$2,400.00 Percent Replacement 100%

10 Linear Feet

Future Cost

@ \$240.00

\$3,317.13

Placed in Service
Useful Life

Replacement Year
Remaining Life

June 2012
30
31-32
9

Fitness Center

Reception Desk Solid St	urface Top - 2031		
Asset ID	1048	24 Linear Feet Asset Actual Cost Percent Replacement	@ \$160.00 \$3,840.00 100%
	Fitness Center	Future Cost	\$5,307.42
Placed in Service	June 2012		
Useful Life	20		
Replacement Year	31-32		
Remaining Life	9		
Refurbishment Allowand	ce - Restrooms - 203	1	
		600 Square Feet	@ \$64.00
Asset ID	1051	Asset Actual Cost	\$38,400.00
		Percent Replacement	100%
	Fitness Center	Future Cost	\$53,074.15
Placed in Service	June 2012		
Useful Life	20		
Replacement Year	31-32		
Remaining Life	9		
Water Cooler - ADA Bi-	Level - 2028	1 Each	@ \$6,000.00
Asset ID	1045	Asset Actual Cost	\$6,000.00
Asset ID	1043	Percent Replacement	100%
	Fitness Center	Future Cost	\$7,589.12
Placed in Service	June 2012	Tuture Cost	Ψ1,507.12
Useful Life	15		
Adjustment	2		
Replacement Year	28-29		
Remaining Life	6		

Wood Flooring Refinishing - Cardio Room - 2031

	900 Square Feet	@ \$2.00
1046	Asset Actual Cost	\$1,800.00
	Percent Replacement	100%
Fitness Center	Future Cost	\$2,487.85
June 2012		
10		
10		
31-32		
9		
	Fitness Center June 2012 10 10 31-32	Asset Actual Cost Percent Replacement Fitness Center June 2012 10 10 31-32



Basketball Poles & C	Goals - 2029	4 Each	@ \$1,800.00
Asset ID	1081	Asset Actual Cost	\$7,200.00
	Basketball Courts	Percent Replacement Future Cost	100% \$9,380.15
Placed in Service	June 2003	Tatale Cost	Ψ2,300.13
Useful Life	15		
Adjustment	12		
Replacement Year	29-30		
Remaining Life	7		
	,		
Chain Link Fence - 2	029	397 Linear Feet	@ \$31.00
Asset ID	1080	Asset Actual Cost	
Asset ID	1000	Percent Replacement	\$12,307.00 100%
	Basketball Courts	Future Cost	\$16,033.55
Placed in Service	June 2003	Tuture Cost	Ψ10,033.33
Useful Life	22		
Adjustment	5		
Replacement Year	29-30		
replacement real	-) 50		
Remaining Life	7		
Remaining Life			
		1,060 Square Yards	@ \$7.00
Remaining Life		1,060 Square Yards Asset Actual Cost	\$7,420.00
Remaining Life Court Resurfacing - 2	1079	Asset Actual Cost Percent Replacement	\$7,420.00 100%
Remaining Life Court Resurfacing - 2 Asset ID	2025 1079 Basketball Courts	Asset Actual Cost	\$7,420.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service	1079	Asset Actual Cost Percent Replacement	\$7,420.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life	2025 1079 Basketball Courts June 2021 5	Asset Actual Cost Percent Replacement	\$7,420.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year	2025 1079 Basketball Courts June 2021 5 25-26	Asset Actual Cost Percent Replacement	\$7,420.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life	2025 1079 Basketball Courts June 2021 5	Asset Actual Cost Percent Replacement	@ \$7.00 \$7,420.00 100% \$8,588.80
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life	2025 1079 Basketball Courts June 2021 5 25-26	Asset Actual Cost Percent Replacement	\$7,420.00 100% \$8,588.80
Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029	2025 1079 Basketball Courts June 2021 5 25-26 3	Asset Actual Cost Percent Replacement Future Cost 4 Each	\$7,420.00 100% \$8,588.80 @ \$3,000.00
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life	2025 1079 Basketball Courts June 2021 5 25-26	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost	\$7,420.00 100% \$8,588.80 @ \$3,000.00 \$12,000.00
Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029	2025 1079 Basketball Courts June 2021 5 25-26 3	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost Percent Replacement	\$7,420.00 100% \$8,588.80 @ \$3,000.00 \$12,000.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029 Asset ID	Basketball Courts June 2021 5 25-26 3 1082 Basketball Courts	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost	\$7,420.00 100% \$8,588.80 @ \$3,000.00 \$12,000.00 100%
Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029 Asset ID Placed in Service	Basketball Courts June 2021 5 25-26 3 1082 Basketball Courts June 2003	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost Percent Replacement	\$7,420.00 100% \$8,588.80 @ \$3,000.00 \$12,000.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029 Asset ID Placed in Service Useful Life	Basketball Courts June 2021 5 25-26 3 1082 Basketball Courts June 2003 25	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost Percent Replacement	\$7,420.00 100% \$8,588.80 @ \$3,000.00 \$12,000.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029 Asset ID Placed in Service Useful Life Adjustment	2025 1079 Basketball Courts June 2021 5 25-26 3 1082 Basketball Courts June 2003 25 2	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost Percent Replacement	\$7,420.00 100% \$8,588.80 @ \$3,000.00 \$12,000.00 100%
Remaining Life Court Resurfacing - 2 Asset ID Placed in Service Useful Life Replacement Year Remaining Life Light Poles - 2029 Asset ID Placed in Service Useful Life	Basketball Courts June 2021 5 25-26 3 1082 Basketball Courts June 2003 25	Asset Actual Cost Percent Replacement Future Cost 4 Each Asset Actual Cost Percent Replacement	\$7,420.00 100%

Chain Link Fence - 10 Ft	- 2029	774 Linear Feet	@ \$31.00
Asset ID	1086	Asset Actual Cost	\$23,994.00
		Percent Replacement	100%
DI 1: C :	Tennis Courts	Future Cost	\$31,259.36
Placed in Service	June 2003		
Useful Life	24		
Adjustment	3		
Replacement Year	29-30		
Remaining Life	7		
Chain Link Fence - 4 Ft -	2029	240 Linear Feet	@ \$19.00
Asset ID	1084	Asset Actual Cost	@ \$18.00 \$4,320.00
Asset ID	1004	Percent Replacement	100%
	Tennis Courts	Future Cost	\$5,628.09
Placed in Service	June 2003	Tuture Cost	ψ3,020.07
Useful Life	24		
Adjustment	3		
Replacement Year	29-30		
Remaining Life	7		
Court Resurfacing - 2025		2,688 Square Yards	@ \$7.00
Asset ID	1085	Asset Actual Cost	\$18,816.00
		Percent Replacement	100%
	Tennis Courts	Future Cost	\$21,779.90
Placed in Service	June 2021		
Useful Life	5		
Replacement Year	25-26		
Remaining Life	3		
Light Poles 2020			
Light Poles - 2029		8 Each	@ \$3,000.00
Asset ID	1087	Asset Actual Cost	\$24,000.00
	T	Percent Replacement	100%
Dlagad in Carria	Tennis Courts	Future Cost	\$31,267.17
Placed in Service	June 2003		
TI C - 1 T : C -	0 <i>E</i>		
Useful Life	25		
Adjustment	2		

Shade Structures - 2024		2 Each	@ \$3,900.00
Asset ID	1083	Asset Actual Cost	\$7,800.00
		Percent Replacement	100%
	Tennis Courts	Future Cost	\$8,681.40
Placed in Service	June 2003		
Useful Life	22		
Replacement Year	24-25		
Remaining Life	2		

Aluminium Fence - 2032		860 Linear Feet	@ \$36.00
Asset ID	1022	Asset Actual Cost Percent Replacement	\$30,960.00 100%
Swimming	g Pool - General	Future Cost	\$44,074.77
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		
Lane Divider Reel - 2027		1 Each	@ \$1,940.00
Asset ID	1025	Asset Actual Cost	\$1,940.00
Asset ID	1023	Percent Replacement	100%
Swimming	g Pool - General	Future Cost	\$2,382.34
Placed in Service	June 2003	Tuture Cost	Ψ2,302.34
Useful Life	20		
Adjustment	5		
Replacement Year	27-28		
Remaining Life	5		
Lane Dividers - 2022		7 Lanes	@ \$520.00
Asset ID	1024	Asset Actual Cost Percent Replacement	\$3,640.00 100%
Swimming	g Pool - General	Future Cost	\$3,640.00
Placed in Service	June 2003		
Useful Life	10		
Adjustment	6		
Replacement Year	22-23		
Remaining Life	0		
Lifeguard Chairs - 2023		2 Fach	@ \$1 400 00
Asset ID	1021	2 Each Asset Actual Cost	@ \$1,400.00 \$2,800.00
Asset ID	1021	Percent Replacement	\$2,800.00 100%
Carimmin	g Pool - General	Future Cost	\$2,968.00
Placed in Service	June 2003	Tuture Cost	Ψ2,900.00
Useful Life	15		
Adjustment	6		
Replacement Year	23-24		
Remaining Life	1		

Pool Furniture Replacement Allowance - 2026

Asset ID	1023	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$40,000.00 \$40,000.00 100%
Swimn	ning Pool - General	Future Cost	\$47,689.82
Placed in Service	June 2019		
Useful Life	8		
Replacement Year	26-27		
Remaining Life	4		

Pool Lift - 2024

	2 Each	@ \$3,200.00
1026	Asset Actual Cost	\$6,400.00
	Percent Replacement	100%
ming Pool - General	Future Cost	\$7,123.20
June 2003		
15		
7		
24-25		
2		
	ming Pool - General June 2003 15	1026 Asset Actual Cost Percent Replacement ming Pool - General June 2003 15 7

Pool Play Equipment Allowance - 2025

Asset ID	1027	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$35,000.00 \$35,000.00 100%
Swi	imming Pool - General	Future Cost	\$40,513.20
Placed in Service	June 2003		
Useful Life	20		
Adjustment	3		
Replacement Year	25-26		
Remaining Life	3		

Pool Pumps & Equipment Annual Allowance - 2022

Asset ID	1020	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$5,000.00 \$5,000.00 100%
Swimm	ing Pool - General	Future Cost	\$5,000.00
Placed in Service	June 2015		
Useful Life	1		
Replacement Year	22-23		
Remaining Life	0		

Pool Resurfacing/Tile - 2029

	1 Lump Sum	@ \$228,000.00
1019	Asset Actual Cost	\$228,000.00
	Percent Replacement	100%
- General	Future Cost	\$297,038.16
	1017	1019 Asset Actual Cost Percent Replacement

Placed in Service
Useful Life
Replacement Year
Remaining Life
February 2015
29-30
7



Asphalt Shingles - 2022		18 Squares	@ \$440.00
Asset ID	1032	Asset Actual Cost	\$7,920.00
		Percent Replacement	100%
	Pool House	Future Cost	\$7,920.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		
Exterior Painting - 2022		3,500 Square Feet	@ \$2.00
Asset ID	1029	Asset Actual Cost	\$7,000.00
Asset ID	102)	Percent Replacement	100%
	Pool House	Future Cost	\$7,000.00
Placed in Service	June 2012	Tatale Cost	Ψ7,000.00
Useful Life	10		
Replacement Year	22-23		
Remaining Life	0		
Refurbishment Allowance	ee - Restrooms - 202	22	
		1 Lump Sum	@ \$6,200.00
Asset ID	1031	Asset Actual Cost	\$6,200.00
	D 177	Percent Replacement	100%
D. 1. G.	Pool House	Future Cost	\$6,200.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		
Standing Seam Metal Ro	oof - 2037	100 Square Feet	@ \$16.00
Asset ID	1028	Asset Actual Cost	\$1,600.00
		Percent Replacement	100%
	Pool House	Future Cost	\$2,640.55
Placed in Service	June 2003		. ,
Useful Life	35		
Replacement Year	37-38		
Replacement Year Remaining Life			

Exterior Painting - P	Pavilion - 2031	1 Lump Sum	@ \$4,000.00
Asset ID	1161	Asset Actual Cost	\$4,000.00
		Percent Replacement	100%
	Pool Shade Structures	Future Cost	\$5,528.56
Placed in Service	May 2022		
Useful Life	10		
Replacement Year	31-32		
Remaining Life	9		
		_	
Standing Seam Meta	al Roof - Pavilion - 203	7	
		1,662 Square Feet	@ \$16.00
Asset ID	1160	Asset Actual Cost	\$26,592.00
		Percent Replacement	100%
	Pool Shade Structures	Future Cost	\$43,886.02
Placed in Service	June 2003		
Useful Life	35		
Replacement Year	37-38		
Remaining Life	15		
Wood Pergola Repla	acement - 2027		
		1,280 Square Feet	@ \$28.00
Asset ID	1162	Asset Actual Cost	\$35,840.00
		Percent Replacement	100%
	Pool Shade Structures	Future Cost	\$44,011.98
Placed in Service	June 2003		,
Useful Life	20		
Adjustment	5		
Replacement Year	27-28		
Remaining Life	5		

Aluminium Railings - Pool Slide Tower - 2027

		160 Linear Feet	@ \$64.00
Asset ID	1166	Asset Actual Cost	\$10,240.00
		Percent Replacement	100%
	Pool Slide & Tower	Future Cost	\$12,574.85
Placed in Service	June 2003		
Useful Life	25		
Replacement Year	27-28		
Remaining Life	5		

Pool Slide Refurbishment Allowance - 2028

Asset ID	1167	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$16,000.00 \$16,000.00 100%
	Pool Slide & Tower	Future Cost	\$20,237.65
Placed in Service	June 2019		
Useful Life	10		
Replacement Year	28-29		
Remaining Life	6		

Pool Slide Tower Painting - 2023

ol Slide Tower Pai	nting - 2023	1 Lump Sum	@ \$12,000.00
Asset ID	1168	Asset Actual Cost	\$12,000.00
		Percent Replacement	100%
	Pool Slide & Tower	Future Cost	\$12,720.00
Placed in Service	June 2010		
Useful Life	10		
Adjustment	4		
Replacement Year	23-24		
Remaining Life	1		

Shade Structures - Pool Side Tower - 2030

Asset ID 1164 Asset Actual Cost \$18,000.00

Percent Replacement Future Cost \$24,153.89

Placed in Service
Useful Life
15
Replacement Year
Remaining Life
June 2016
30-31
8



Standing Seam Metal Roof - Slide Tower - 2037

Asset ID 1165 Asset Actual Cost \$6,400.00
Percent Replacement 100%
Pool Slide & Tower Future Cost \$10,562.22

Placed in Service
Useful Life
35
Replacement Year
Remaining Life
June 2003
37-38

Bi-pod Swing Set - Two Bay - 2022

Asset ID 1110

Park - Fall Creek
Placed in Service
Useful Life
Replacement Year
Remaining Life
Park - Fall Creek
June 2003
22-23
22-23



Gazebo Roof - 2032

Asset ID

600 Square Feet Asset Actual Cost Percent Replacement

Future Cost

@ \$8.00
\$4,800.00
100%

\$6,833.30

Placed in Service
Useful Life
Replacement Year
Remaining Life

June 2003 30 32-33 10

Park - Fall Creek

1107



Park Benches -Back to Back - 2022

Asset ID 1108 Asset Actual Cost \$2,300.00 Percent Replacement 100%

Park - Fall Creek
Placed in Service
Useful Life
Adjustment
Replacement Year
Remaining Life
Park - Fall Creek
June 2003
2023
2223



Picnic Table - 2022

Asset ID 1111 Asset Actual Cost \$2,600.00 Percent Replacement 100%

Placed in Service
Useful Life
Adjustment
3
Replacement Year
Remaining Life
June 2003
22-23
22-23

Park - Fall Creek

2 Each @ \$1,300.00
Asset Actual Cost \$2,600.00
Percent Replacement 100%
Future Cost \$2,600.00

1 Each

Future Cost

@ \$2,300.00

\$2,300.00



Community Advisors Page 5-60 May 9, 2022

Plastic Play Surface Border - 2022

Asset ID 1109

290 Linear Feet @ \$21.00 Asset Actual Cost \$6,090.00 Percent Replacement 100% Future Cost \$6,090.00

Park - Fall Creek
Placed in Service
Useful Life
Replacement Year
Remaining Life
Park - Fall Creek
June 2003
22-23
22-23



Play Equipment Allowance - 2022

Asset ID 1105

Park - Fall Creek
Placed in Service
Useful Life
Adjustment
Service
Flaced in Service
June 2003
15
Adjustment
5
Replacement Year
Remaining Life
O



Vinyl Ranch Fence - 2032

Asset ID 1106 Asset Actual Cost \$13,248.00
Percent Replacement 100%
Park - Fall Creek Future Cost \$18,859.90

Placed in Service June 2003
Useful Life 30
Replacement Year 32-33
Remaining Life 10



Bi-pod Swing Set - Two Bay - 2035

 ng Set - Iwo Bay - 2035
 1 Each
 @ \$3,200.00

 Asset ID
 1118
 Asset Actual Cost
 \$3,200.00

 Percent Replacement
 100%

 Park - Natures Hammock
 Future Cost
 \$4,977.95

Park - Natures Hammock
Placed in Service
Useful Life
15
Replacement Year

Park - Natures Hammock
Future Cost
5
Future Cost
5
Future Cost

13

Fence/Gates - Dog Park - 2037

Remaining Life

Asset ID 1118 Asset Actual Cost \$9,880.00
Percent Replacement 100%

Park - Natures Hammock Future Cost \$16,305.43 Placed in Service June 2020

Useful Life 18
Replacement Year 37-38
Remaining Life 15



Gazebo Roof - 2032

Asset ID 1115 Asset Actual Cost \$4,800.00
Percent Replacement 100%

Park - Natures Hammock Future Cost \$6,833.30
Placed in Service June 2003
Useful Life 30

Replacement Year 32-33 Remaining Life 10

Gazebo Roof continued...



Park Benches -Back to Back - 2036

Asset ID 1119 Asset Actual Cost \$2,300.00
Percent Replacement 100%
Park - Natures Hammock Future Cost \$3,685.24

Placed in Service June 2021
Useful Life 16
Replacement Year 36-37
Remaining Life 14



Picnic Table - 2036

Asset ID 1120 Asset Actual Cost \$2,600.00
Percent Replacement 100%
Park - Natures Hammock Future Cost \$4,165.92

2 Each

@ \$1,300.00

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2021
36-37
14

Community Advisors Page 5-64 May 9, 2022

Picnic Table continued...



Plastic Play Surface Border - 2040

Asset ID 1112

Park - Natures Hammock

Placed in Service June 2021
Useful Life 20
Replacement Year 40-41
Remaining Life 18

280 Linear Feet @ \$21.00
Asset Actual Cost \$5,880.00
Percent Replacement 100%
Future Cost \$10,603.86



Play Equipment Allowance - 2035

Asset ID 1114

Park - Natures Hammock

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2021
35-36
Remaining Life

Community Advisors Page 5-65 May 9, 2022

Play Equipment Allowance continued...



Scoop Digger - 2035 Asset ID	1117	1 Each Asset Actual Cost Percent Replacement	@ \$2,100.00 \$2,100.00 100%
Park -	- Natures Hammock	Future Cost	\$3,266.78
Placed in Service	June 2021	1 00010 0000	¢2, 2 00.70
Useful Life	15		
Replacement Year	35-36		
Remaining Life	13		
Vinyl Ranch Fence - 20	032	232 Linear Feet	@ \$24.00
Asset ID	1113	Asset Actual Cost	\$5,568.00
		Percent Replacement	100%
Park -	- Natures Hammock	Future Cost	\$7,926.62
Placed in Service	June 2003		
Useful Life	30		

32-33

10

Replacement Year

Remaining Life

Vinyl Ranch Fence continued...



Bi-pod Swing Set - To	wo Bay - 2022	1 Each	@ \$3,200.00
Asset ID	1122	Asset Actual Cost	\$3,200.00 100%
	Park - Timberfield	Percent Replacement Future Cost	\$3,200.00
Placed in Service	June 2003	Tuture Cost	φ2,200.00
Useful Life	15		
Replacement Year	22-23		
Remaining Life	0		
Remaining Zite	v		
Gazebo Roof - 2032		600 Square Feet	@ \$6.20
Asset ID	1121	Asset Actual Cost	\$3,720.00
Asset ID	1121		100%
	Park - Timberfield	Percent Replacement Future Cost	\$5,295.81
Placed in Service	June 2003	ruture Cost	φ3,293.61
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		
Remaining Life	10		
Park Benches -Back t	to Back - 2022		
Asset ID	1123	Asset Actual Cost	\$2,300.00
		Percent Replacement	100%
	Park - Timberfield	Future Cost	\$2,300.00
Placed in Service	June 2003		,
Useful Life	16		
Adjustment	4		
Replacement Year	22-23		
Remaining Life	0		
Picnic Table - 2022			Θ ¢1 200 00
	1105	2 Each	@ \$1,300.00
Asset ID	1125	Asset Actual Cost	\$2,600.00
	D 1 75' 1 6' 11	Percent Replacement	100%
DI1: 0 '	Park - Timberfield	Future Cost	\$2,600.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		

Plastic Play Surface F	Border - 2022	330 Linear Feet	@ \$21.00
Asset ID	1127	Asset Actual Cost	\$6,930.00
		Percent Replacement	100%
	Park - Timberfield	Future Cost	\$6,930.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		

2	1 Lumn Sum	@ \$30,000.00
	-	\$30,000.00
	Percent Replacement	100%
nberfield	Future Cost	\$30,000.00
ine 2003		
15		
5		
22-23		
0		
(5 22-23	Asset Actual Cost Percent Replacement The sum of the second secon

Vinyl Ranch Fence - 203	32	554 Linear Feet	@ \$24.00
Asset ID	1124	Asset Actual Cost	\$13,296.00
		Percent Replacement	100%
]	Park - Timberfield	Future Cost	\$18,928.23
Placed in Service	June 2003		
Useful Life	30		

32-33 10

Replacement Year Remaining Life



Bi-pod Swing Set - Tv	wo Bay - 2022	1 Each	@ \$3,200.00
Asset ID	1128	Asset Actual Cost Percent Replacement	\$3,200.00 100%
	Park - Stonebrier	Future Cost	\$3,200.00
Placed in Service	June 2003	Tutare cost	Ψ5,200.00
Useful Life	15		
Replacement Year	22-23		
Remaining Life	0		
Remaining Dife	v		
Gazebo Roof - 2032		600 Square Feet	@ \$8.00
Asset ID	1131	Asset Actual Cost	\$4,800.00
Asset ID	1131	Percent Replacement	100%
	Park - Stonebrier	Future Cost	\$6,833.30
Placed in Service	June 2003	ruture Cost	ψ0,033.30
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		
Park Benches -Back t	o Back - 2023		
Asset ID	1133	Asset Actual Cost	\$2,300.00
		Percent Replacement	100%
	Park - Stonebrier	Future Cost	\$2,438.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	5		
Replacement Year	23-24		
Remaining Life	1		
Picnic Table - 2022		2 Each	@ \$1,300.00
Asset ID	1136	Asset Actual Cost	\$2,600.00
ASSELID	1130	Percent Replacement	\$2,000.00 100%
	Park - Stonebrier	Future Cost	\$2,600.00
Placed in Service	June 2003	Tuture Cost	Ψ2,000.00
Useful Life	16		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		
Remaining Diffe	U		

@ \$21.00	260 Linear Feet	order - 2022	Plastic Play Surface Bo
\$5,460.00	Asset Actual Cost	1135	Asset ID
100%	Percent Replacement		
\$5,460.00	Future Cost	Park - Stonebrier	DI 1' G '
		June 2003	Placed in Service
		20	Useful Life
		22-23 0	Replacement Year
		U	Remaining Life
@ \$30,000.00	1 Lump Sum	vance - 2022	Play Equipment Allow
\$30,000.00	Asset Actual Cost	1129	Asset ID
100%	Percent Replacement		
\$30,000.00	Future Cost	Park - Stonebrier	
,		June 2003	Placed in Service
		15	Useful Life
		5	Adjustment
		22-23	Replacement Year
		0	Remaining Life
@ \$2,100.00	1 Each		Scoop Digger - 2022
\$2,100.00	Asset Actual Cost	1132	Asset ID
100%	Percent Replacement	1132	Asset ID
\$2,100.00	Future Cost	Park - Stonebrier	
+-,	- 33332 - 233	June 2003	Placed in Service
		15	Useful Life
		3	Adjustment
		22-23	Replacement Year
		0	Remaining Life
O 01 500 00			Spring Rider - 2022
@ \$1,600.00	1 Each	1120	
\$1,600.00	Asset Actual Cost	1130	Asset ID
100% \$1,600.00	Percent Replacement	Doule Chousehaire	
かしのいいい	Future Cost	Park - Stonebrier June 2003	Placed in Service
4-,000.00		June Zuub	Flaceu III Service
+ -, · · · · · ·			Heaful Life
4 - 4 - 4		15	Useful Life
¥ -,000000			Useful Life Adjustment Replacement Year

Vinyl Ranch Fence - 2027		606 Linear Feet	@ \$24.00
Asset ID	1134	Asset Actual Cost	\$14,544.00
		Percent Replacement	100%
Parl	k - Stonebrier	Future Cost	\$17,860.22
Placed in Service	June 2003		
Useful Life	30		
Adjustment	-5		
Replacement Year	27-28		
Remaining Life	5		

Bi-pod Swing Set - Two	Bay - 2022	1 Each	@ \$3,200.00
Asset ID	1138	Asset Actual Cost Percent Replacement	\$3,200.00 100%
Park - V	Worthngton Oaks	Future Cost	\$3,200.00
Placed in Service	June 2003	Tatare Cost	Ψ5,200.00
Useful Life	15		
Replacement Year	22-23		
Remaining Life	0		
Remaining Life	U		
Gazebo Roof - 2032		600 Square Feet	@ \$8.00
Asset ID	1140	Asset Actual Cost	\$4,800.00
Asset ID	1140	Percent Replacement	100%
Dark V	Worthngton Oaks	Future Cost	\$6,833.30
Placed in Service	June 2003	Tuture Cost	\$0,655.50
Useful Life	30		
	32-33		
Replacement Year Remaining Life	10		
210111111111111111111111111111111111111			
Park Benches -Back to B	ack - 2022	1 Each	@ \$2,300.00
Asset ID	1143	Asset Actual Cost	\$2,300.00
		Percent Replacement	100%
Park - V	Worthngton Oaks	Future Cost	\$2,300.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		
Picnic Table - 2022		2 Each	@ \$1,300.00
Asset ID	1142	Asset Actual Cost	\$2,600.00
Asset ID	1142	Percent Replacement	100%
Park _ V	Worthngton Oaks	Future Cost	\$2,600.00
Placed in Service	June 2003	i didic Cost	Ψ2,000.00
Useful Life	16		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		
Kemannig Life	U		

Plastic Play Surface Border	- 2022	310 Linear Feet	@ \$21.00
Asset ID	1137	Asset Actual Cost	\$6,510.00
		Percent Replacement	100%
Park - Woi	rthngton Oaks	Future Cost	\$6,510.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		
Play Equipment Allowance	- 2022	1 Lump Sum	@ \$30,000.00
Asset ID	1139	Asset Actual Cost	\$30,000.00
		Percent Replacement	100%
Park - Woi	rthngton Oaks	Future Cost	\$30,000.00
Placed in Service	June 2003		. ,
Useful Life	15		
Adjustment	5		
Replacement Year	22-23		
Remaining Life	0		
Winyal Donah Fance 2022			
Vinyl Ranch Fence - 2032		410 Linear Feet	@ \$24.00
Asset ID	1141	Asset Actual Cost	\$9,840.00
		Percent Replacement	100%
	rthngton Oaks	Future Cost	\$14,008.26
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

Gazebo Roof - 2032

Asset ID 1089 Asset Actual Cost \$4,800.00
Percent Replacement 100%
Park - Oakbrook Future Cost \$6,833.30

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
June 2003
32-33
10



Park Bench - 2022

Asset ID 1090 Asset Actual Cost \$1,300.00 Percent Replacement 100%

1 Each

Future Cost

@ \$1,300.00

\$1,300.00

Placed in Service June 2003
Useful Life 16
Replacement Year 22-23
Remaining Life 0

Park - Oakbrook



Picnic Table - 2022		1 Each	@ \$1,300.00
Asset ID	1088	Asset Actual Cost	\$1,300.00
		Percent Replacement	100%
	Park - Oakbrook	Future Cost	\$1,300.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	2		
Replacement Year	22-23		
Remaining Life	0		



Bi-pod Swing Set - Two Bay - 2022

Asset ID 1094

Park - Silverleaf
Placed in Service
Useful Life
Replacement Year
Remaining Life
Park - Silverleaf
June 2003
22-23
22-23



Gazebo Roof - 2032

Asset ID

1093

600 Square Feet Asset Actual Cost Percent Replacement Future Cost @ \$8.00
\$4,800.00
100%
\$6,833.30

Park - Silverleaf
Placed in Service
Useful Life
Replacement Year
Remaining Life
Park - Silverleaf
June 2003
32-33



Park Benches -Back to Back - 2023

Asset ID 1095 Asset Actual Cost \$2,300.00

Percent Replacement 100%

Park - Silverleaf Future Cost \$2,438.00

Placed in Service June 2003
Useful Life 16
Adjustment 5
Replacement Year 23-24
Remaining Life 1



Picnic Table - 2022

Asset ID 1097 Asset Actual Cost \$2,600.00 Percent Replacement 100%

Park - Silverleaf
Placed in Service
Useful Life
Adjustment
Replacement Year
Remaining Life
Park - Silverleaf
June 2003
2203
22-23

2 Each @ \$1,300.00
Asset Actual Cost \$2,600.00
Percent Replacement 100%
Future Cost \$2,600.00



Community Advisors Page 5-78 May 9, 2022

Plastic Play Surface Border - 2022

Asset ID 1092

250 Linear Feet @ \$21.00 Asset Actual Cost \$5,250.00 Percent Replacement 100% Future Cost \$5,250.00

Park - Silverleaf
Placed in Service
Useful Life
Replacement Year
Remaining Life
Park - Silverleaf
June 2003
22-23



Play Equipment Allowance - 2035

Asset ID 1091

Park - Silverleaf
Placed in Service
Useful Life
Replacement Year
Remaining Life
Park - Silverleaf
June 2021
35-36





Vinyl Ranch Fence - 2032

Asset ID 1096 Asset Actual Cost \$10,896.00
Percent Replacement 100%
Park - Silverleaf Future Cost \$15,511.58

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
June 2003
32-33



Bi-Pod Swing Set On	e Bay - 2022	1 Each	@ \$2,200.00
Asset ID	1159	Asset Actual Cost Percent Replacement	\$2,200.00 100%
Placed in Service Useful Life Replacement Year Remaining Life	Park - Club House June 2003 15 22-23 0	Future Cost	\$2,200.00
Bi-Pod Swing Set Tw	yo Bay - 2022	1 Each	@ \$3,200.00
Asset ID	1154	Asset Actual Cost Percent Replacement	\$3,200.00 100%
Placed in Service Useful Life Replacement Year Remaining Life	Park - Club House June 2003 15 22-23 0	Future Cost	\$3,200.00
Park Benches - 2022		8 Each	@ \$1,300.00
Asset ID	1155	Assat Astrol Cost	
	1133	Asset Actual Cost Percent Replacement	\$10,400.00 100%
	Park - Club House		
Placed in Service	Park - Club House June 2003	Percent Replacement	100%
	Park - Club House	Percent Replacement	100%
Placed in Service Useful Life Adjustment Replacement Year	Park - Club House June 2003 16 3 22-23	Percent Replacement	100%
Placed in Service Useful Life Adjustment	Park - Club House June 2003 16 3	Percent Replacement	100%
Placed in Service Useful Life Adjustment Replacement Year Remaining Life	Park - Club House June 2003 16 3 22-23 0	Percent Replacement Future Cost	100% \$10,400.00
Placed in Service Useful Life Adjustment Replacement Year	Park - Club House June 2003 16 3 22-23 0	Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost	100% \$10,400.00 @ \$30,000.00 \$30,000.00
Placed in Service Useful Life Adjustment Replacement Year Remaining Life Play Equipment - 202	Park - Club House June 2003 16 3 22-23 0	Percent Replacement Future Cost 1 Lump Sum	100% \$10,400.00 @ \$30,000.00
Placed in Service Useful Life Adjustment Replacement Year Remaining Life Play Equipment - 202 Asset ID Placed in Service	Park - Club House June 2003 16 3 22-23 0 1157 Park - Club House June 2003	Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	100% \$10,400.00 \$30,000.00 \$30,000.00 100%
Placed in Service Useful Life Adjustment Replacement Year Remaining Life Play Equipment - 202 Asset ID Placed in Service Useful Life	Park - Club House June 2003 16 3 22-23 0 1157 Park - Club House June 2003 15	Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	100% \$10,400.00 \$30,000.00 \$30,000.00 100%
Placed in Service Useful Life Adjustment Replacement Year Remaining Life Play Equipment - 202 Asset ID Placed in Service Useful Life Adjustment	Park - Club House June 2003 16 3 22-23 0 1157 Park - Club House June 2003 15 5	Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	100% \$10,400.00 \$30,000.00 \$30,000.00 100%
Placed in Service Useful Life Adjustment Replacement Year Remaining Life Play Equipment - 202 Asset ID Placed in Service Useful Life	Park - Club House June 2003 16 3 22-23 0 1157 Park - Club House June 2003 15	Percent Replacement Future Cost 1 Lump Sum Asset Actual Cost Percent Replacement	100% \$10,400.00 \$30,000.00 \$30,000.00 100%

Scoop Digger - 2022		1 Each	@ \$2,100.00
Asset ID	1158	Asset Actual Cost	\$2,100.00
		Percent Replacement	100%
	Park - Club House	Future Cost	\$2,100.00
Placed in Service	June 2003		
Useful Life	15		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		
Spring Rider - 2022		3 Each	@ \$1,600.00
Spring Rider - 2022 Asset ID	1156	3 Each Asset Actual Cost	@ \$1,600.00 \$4,800.00
	1156		•
	1156 Park - Club House	Asset Actual Cost	\$4,800.00
		Asset Actual Cost Percent Replacement	\$4,800.00 100%
Asset ID	Park - Club House	Asset Actual Cost Percent Replacement	\$4,800.00 100%
Asset ID Placed in Service	Park - Club House June 2003	Asset Actual Cost Percent Replacement	\$4,800.00 100%
Asset ID Placed in Service Useful Life	Park - Club House June 2003 15	Asset Actual Cost Percent Replacement	\$4,800.00 100%

Play Equipment Allowance - Playground - 2022

Asset ID	1199	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$30,000.00 \$30,000.00 100%
	Park - Sport Field	Future Cost	\$30,000.00
Placed in Service	June 2003		
Useful Life	15		
Adjustment	5		
Replacement Year	22-23		
Remaining Life	0		



Scoop Digger - Playground - 2022

coop Digger - Playground - 2022		1 Each	@ \$2,100.00
Asset ID	1201	Asset Actual Cost	\$2,100.00
		Percent Replacement	100%
	Park - Sport Field	Future Cost	\$2,100.00
Placed in Service	June 2003		
Useful Life	15		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		

Spring Rider - Playground - 2022

@ \$1,600.00 1 Each Asset ID 1200 Asset Actual Cost \$1,600.00 Percent Replacement 100% Park - Sport Field Future Cost \$1,600.00

Placed in Service June 2003 Useful Life 15 3 Adjustment 22-23 Replacement Year Remaining Life 0



Bi-pod Swing Set - Tw	Bi-pod Swing Set - Two Bay - 2022		@ \$3,200.00
Asset ID	1099	Asset Actual Cost Percent Replacement	\$3,200.00 100%
	Park - The Oaks	Future Cost	\$3,200.00
Placed in Service	June 2003		. ,
Useful Life	15		
Replacement Year	22-23		
Remaining Life	0		
Gazebo Roof - 2032		600 Square Feet	@ \$8.00
Asset ID	1102	Asset Actual Cost	\$4,800.00
	1102	Percent Replacement	100%
	Park - The Oaks	Future Cost	\$6,833.30
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		
Park Benches - 2022		1 Each	@ \$1,300.00
Asset ID	1100	Asset Actual Cost	\$1,300.00
		Percent Replacement	100%
	Park - The Oaks	Future Cost	\$1,300.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	1		
Replacement Year	22-23		
Remaining Life	0		
Picnic Table - 2022		2 Each	@ \$1,300.00
Asset ID	1103	Asset Actual Cost	\$2,600.00
		Percent Replacement	100%
	Park - The Oaks	Future Cost	\$2,600.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	2		
Adjustment Replacement Year Remaining Life	2 22-23 0		

Plastic Play Surface I	Border - 2022	260 Linear Feet	@ \$21.00
Asset ID	1104	Asset Actual Cost	\$5,460.00
		Percent Replacement	100%
	Park - The Oaks	Future Cost	\$5,460.00
Placed in Service	June 2003		
Useful Life	20		
Replacement Year	22-23		
Remaining Life	0		
Play Equipment Allow	wance - 2022	1 Lump Sum	@ \$30,000.00
Asset ID	1098	Asset Actual Cost	\$30,000.00
		Percent Replacement	100%
	Park - The Oaks	Future Cost	\$30,000.00
Placed in Service	June 2003		
Useful Life	15		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		
Vinyl Ranch Fence -	2032	200 Linear Feet	@ \$24.00
Asset ID	1101	Asset Actual Cost	\$4,800.00
		Percent Replacement	100%
	Park - The Oaks	Future Cost	\$6,833.30
Placed in Service	June 2003		
Useful Life	30		
Replacement Year	32-33		
Remaining Life	10		

@ \$3,200.00	1 Each	Bi-pod Swing Set - Two Bay - 2022	
\$3,200.00 100%	Asset Actual Cost Percent Replacement	1145	Asset ID
\$3,200.00	Future Cost	Park - Cannons Point	
Ψ3,200.00	Tuture Cost	June 2003	Placed in Service
		15	Useful Life
		22-23	Replacement Year
		0	Remaining Life
		· ·	Remaining Dire
@ \$2,800.00	1 Each	022	Cresent Climber - 20
\$2,800.00	Asset Actual Cost	1151	Asset ID
100%	Percent Replacement	1131	Asset ID
\$2,800.00	Future Cost	Park - Cannons Point	
Ψ2,000.00	Tatare Cost	June 2003	Placed in Service
		18	Useful Life
		22-23	Replacement Year
		0	Remaining Life
			, and the second
@ \$8.00	600 Square Feet		Gazebo Roof - 2032
\$4,800.00	Asset Actual Cost	1148	Asset ID
100%	Percent Replacement		
\$6,833.30	Future Cost	Park - Cannons Point	
		June 2003	Placed in Service
		30	Useful Life
		32-33	Replacement Year
		10	Remaining Life
		4- D1- 2022	Davida Davida a Davida
			Park Benches -Back
\$2,300.00 100%	Asset Actual Cost Percent Replacement	1149	Asset ID
\$2,300.00	Future Cost	Park - Cannons Point	
		June 2003	Placed in Service
		16	Useful Life
		-4	Adjustment
		22-23	Replacement Year
		0	Remaining Life

Picnic Table - 2022		2 Each	@ \$1,300.00
Asset ID	1153	Asset Actual Cost	\$2,600.00
		Percent Replacement	100%
	Park - Cannons Point	Future Cost	\$2,600.00
Placed in Service	June 2003		
Useful Life	16		
Adjustment	3		
Replacement Year	22-23		
Remaining Life	0		

Plastic Play Surface Border - 2022

Asset ID 1152 Asset Actual Cost Percent Replacement 100%
Park - Cannons Point Future Cost \$6,510.00

Placed in Service June 2003
Useful Life 20
Replacement Year 22-23
Remaining Life 0

Play Equipment Allowance - 2022

 ment Allowance - 2022
 1 Lump Sum
 @ \$30,000.00

 Asset ID
 1146
 Asset Actual Cost
 \$30,000.00

 Percent Replacement
 100%

\$30,000.00

Park - Cannons Point Future Cost
Placed in Service June 2003
Useful Life 15
Adjustment 5
Replacement Year 22-23

Replacement Year 22-23 Remaining Life 0



@ \$2,100.00	1 Each		Scoop Digger - 2022
\$2,100.00	Asset Actual Cost	1150	Asset ID
100%	Percent Replacement		
\$2,100.00	Future Cost	Park - Cannons Point	
		June 2003	Placed in Service
		15	Useful Life
		3	Adjustment
		22-23	Replacement Year
		0	Remaining Life
@ \$1 600 00	1 Feeb		Spring Rider - 2022
@ \$1,600.00	1 Each Asset Actual Cost	1144	Asset ID
\$1,600.00 100%		1144	Asset ID
\$1,600.00	Percent Replacement Future Cost	Park - Cannons Point	
\$1,000.00	ruture Cost	June 2003	Placed in Service
			Useful Life
		15 3	
		22-23	Adjustment Replacement Year
		0	Remaining Life
		Ü	Remaining Life
@ \$24.00	365 Linear Feet	2032	Vinyl Ranch Fence -
\$8,760.00	Asset Actual Cost	1147	Asset ID
100%	Percent Replacement		
\$12,470.77	Future Cost	Park - Cannons Point	
•		June 2003	Placed in Service
		30	Useful Life
		32-33	Replacement Year
		10	Remaining Life



Community Advisors Page 5-89 May 9, 2022

Ice Machine - Club Romm

Asset ID 1076 Asset Actual Cost

Percent Replacement 100%
Operating Expense Future Cost

Placed in Service June 2003
No Useful Life

Metal Trash Cans

Asset ID Asset Actual Cost

Percent Replacement 100%
Operating Expense Future Cost

Placed in Service June 2003
No Useful Life

Wood Repair/Painting - Pool Pergola

No Useful Life

Asset ID 1163 Asset Actual Cost
Percent Replacement 100%

Operating Expense Future Cost
Placed in Service June 2003

Cardio Room Wood Floor Replacement

Asset ID Asset Actual Cost Percent Replacement

Components Not Included

Placed in Service June 2003

No Useful Life

Glass Display Refrigerator - 2023

1 Each @ \$2,100.00 Asset ID 1042 Asset Actual Cost \$2,100.00

Percent Replacement 100% **Future Cost** Components Not Included \$2,226.00

Future Cost

100%

Placed in Service June 2010

Useful Life 12 Adjustment 2

Replacement Year 23-24 Remaining Life 1

Ice Machine - 2022

@ \$4,000.00 1 Each Asset ID 1041 Asset Actual Cost \$4,000.00

Percent Replacement 100% **Future Cost** Components Not Included \$4,000.00

Placed in Service June 2003

Useful Life 15 Adjustment 2 22-23

Replacement Year Remaining Life 0

Pool Slide Replacement

Asset ID 1167 **Asset Actual Cost**

Percent Replacement 100% Components Not Included **Future Cost**

Placed in Service June 2019

No Useful Life

Report Navigation

- **Executive Summary** provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Component Funding or Pooled Cash
 - Component Funding Contribution is a year one only amount
 - Current Funding Plan currently used by the Association
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- Cash Flow is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- **Annual Expenditure Detail** provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- Component Detail Index allows quick access to the detail we have included for each component separated into categories
- Component Detail provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

Important Information

Level of Service: Level I Full Reserve Study with a site visit, Level II Update with a site visit or Level III Financial Update with no site visit as defined by the National Reserve Study Standards established by the Community Associations Institute. Component quantity, condition and projected remaining useful life were determined with a visual inspection by the Analyst if a site visit was conducted.

Purpose: This study provides an inventory of major components above a threshold value as determined by the Association that require regular replacement and a plan to fund them.

Basis: Our analysis follows the guidelines for Reserve Studies established by the Association of Professional Reserve Analysts (APRA) and the Community Associations Institute (CAI). Components included in this analysis generally meet the following criteria:

- Component must be owned or maintained by the Association
- Component must have a limited life
- Component must have a predictable useful life
- Component must have a replacement cost above a threshold cost

These guidelines limit reserve components to predictable expenses and do not consider large expenses such as stormwater systems or dredging of the stormwater ponds. While their replacement cost and remaining, useful life may not be predictable they can be expensive, therefore we recommend an allowance be applied for funding which can be adjusted at each update.

Useful life and remaining useful life projections are determined by our visual inspection of each component, our experience with similar communities, your historical records and if required vendor evaluation. The Association may have experienced some replacement cycles for various components with historical cost therefore this information is considered in our analysis. Each cost and useful life was reviewed and compared to similar project we have completed and adjusted as needed. Components with replacement cost over \$1,000 are typically included.

The various component replacement cycles experienced by the Association are driven by the level of quality required by the community, cost of maintenance vs replacement, existing condition, and use. All useful life projections found in this analysis are in the acceptable range for this specific type of community.

Replacement cost for components is driven by local market conditions and available of similar materials. Many components have included repair and refurbishment to extend their useful life and reduce holding cost over time

Funding Goal: The Association may elect for the following goals

- Fully Funded Reserve 100% funding for each component
- Threshold Funded Reserve Annual ending balances are maintained above an adequate or "Threshold" level.

Funding Methods: Reserve analysis typically uses two methods of determining necessary funding levels for component replacement; the Component Method the Cash Flow Method.

- The Component Method provides a reserve contribution amount by estimating the current replacement cost for each component, subtracting that component's current balance which provides the unfunded balance then dividing that total by the number of remaining years of useful life. Each component's contribution is then total for the annual contribution. This method includes inflation of replacement cost and interest on invested funds and provides the least risk of deferred maintenance or special assessment.
- Another version of the Component Method is referred to as "Straight Line Method" which follows the same calculation as above but does not consider interest on funds or inflation on replacement cost. This method only provides a one-year contribution amount and may result in large changes in annual contribution from year to year.
- The Cash Flow Method or pooled method of reserve funding groups component replacement together rather than segregated as in the Component Method. Cash outflows must be offset by contributions and interest earned to maintain adequate funding.
- Cash Flow Method Models include the Current Assessment Funding Model (AFM) and the Threshold Funding Model (TFM) among others.
 - The AFM Model illustrates the current funding projections adopted by the Association and how these perform over time. This model is also used to develop a funding plan with annual contributions entered for each year which allows a custom funding plan.
 - The TFM maintains minimum annual balances or percent funded which are determined by the Analyst or requested by the Association. The year with the lowest ending balance is considered the "Threshold Year" for the total funding plan period.

Conclusion

There are several factors to consider when determining reserve funding levels that include maintaining the quality and value of the community, the ability of the Association to respond to unpredictable component failures and to maintain an acceptable level of risk. Full funding provides the lowest risk of deferred maintenance or special assessment but generally requires large contributions. Threshold Funding keeps reserve balances above predetermined annual balance that provides a moderate risk level with mostly level contributions.

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the Association can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. We recommend Full Funding to avoid deferred maintenance or special assessments. Baseline Funding maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service attention to detail, quick response and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.